DISTRIBUTION OPERATIONAL SAFETY RULES 2022



Intentionally left blank.

Intentionally left blank.

SSEN Distribution Operational Safety Rules 2022



HOW TO USE THESE DISTRIBUTION OPERATIONAL SAFETY RULES

The contents table near the front of these Safety Rules is intended to aid the user to find specific sections of these Rules as appropriate.

Appendix A at the rear of these Safety Rules contains diagrams.

Advice on treatment/ emergency first aid following electric shock is shown on the rear cover.

The right-hand pages provide the written rules and associated detail. Where appropriate, the left-hand pages of these Safety Rules provide facing page notes and other such guidance designed to provide further support for the user.

Typically, the facing page notes refer to **Approved** Procedures located in the Scottish and Southern Electricity Networks Distribution (**SSEN-D**) Operational Safety Manual.

It must be noted that the facing page notes provided in these Safety Rules are not exhaustive and as such additional help and information on **Approved** Procedures or interpretations of these Safety Rules can be obtained from your manager, the **SSEN-D** Operational Safety team, or the **Designated Engineer**.

IMPORTANT – when you receive your copy of these Safety Rules you must do two things without delay:

- 1. Read the Safety Rules and familiarise yourself with the structure and content of the rules. Being able to navigate successfully through these Safety Rules is a key requirement for all **Persons**; and
- 2. Register your ownership of the Distribution Operational Safety Rule book using the QR Code on the opposite page.

SSEN Distribution Operational Safety Rules 2022

If it's not safe, we don't do it.

FOREWORD

These Scottish & Southern Electricity Networks Distribution Safety Rules are based on the Energy Networks Association Model Distribution Safety Rules (MDSR) which provide a set of generic rules that Electricity Companies may use as the foundation of their safety management system for operations on their networks (defined as **System** in the Rules). The MDSR were originally written using experience gained over many years of operating electricity networks and are now regularly reviewed in the light of recent events and the introduction of updated equipment and new technology. Revisions have been included following reviews, and considering lessons learnt from shared incidents.

The MDSR is a copyrighted document and they have been produced and approved by the Safety, Health and Environment Committee of Energy Networks Association. They are written to fulfil a number of extremely important roles:

- The MDSR forms the foundation of safe systems of work formulated by individual companies to fulfil several legal requirements under the Health and Safety at Work Act 1974, the Electricity at Work Regulations 1989, and other applicable statutory instruments;
- They provide a common framework that allows co-operation and safe movement of staff and contractors throughout Great Britain;
- They allow good practice safety standards to be known and shared throughout the industry; and
- Most importantly, they provide guidance to staff and contractors working in the industry to ensure that they are able to work safely and reduce the risk of serious injury to themselves and their colleagues.

The MDSR are a good practice safe system of work within the UK when considering the requirements of the Electricity at Work Regulations 1989 (as amended). The MDSR also aligns with the requirements of BS EN 50110 (Operation of Electrical Installations) at the time of revision.

SSEN Distribution Operational Safety Rules 2022

If you're not sure, stop and ask for help.

TABLE OF CONTENTS

FORE	NORD	3
POLICY		
1.	GENERAL PROVISIONS	9
2.	DEFINITIONS1	7
3.	GENERAL SAFETY PRECAUTIONS	7
4.	SAFETY PRECAUTIONS FOR WORK ON OR NEAR HIGH VOLTAGE SYSTEMS	9
5.	PROCEDURES FOR WORK ON PARTICULAR ITEMS OF PLANT, APPARATUS OR CONDUCTORS7	1
6.	SAFETY PRECAUTIONS FOR HIGH VOLTAGE LIVE LINE WORK ON HIGH VOLTAGE OVERHEAD LINES10	9
7.	SAFETY PRECAUTIONS FOR THE TESTING OF HIGH VOLTAGE APPARATUS	5
8.	SAFETY PRECAUTIONS AND PROCEDURES APPLICABLE TO LOW VOLTAGE SYSTEMS	9
9.	RESPONSIBILITIES OF PERSONS	3
10.	APPENDIX A – WORKING AND ACCESS CLEARANCE DIAGRAMS14	5

Reminder – safety rule 1.7 can be used for objections on safety grounds.

POLICY

P1

SSEN-D Systems and associated Plant and Apparatus for the distribution of electrical energy, at voltages up to and including 132kV, are designed such that they may be operated safely when Approved operational procedures are followed correctly. However, when Switching for operational purposes, or when work such as maintenance, testing and repair has to be carried out or when, particularly, Systems and associated Plant and Apparatus have to be taken temporarily out of normal operational use, it is necessary for the Safety Rules and related documents and procedures to be applied, so as to ensure the health and safety of all who are liable to be affected by any Danger that might arise. These Safety Rules, as read with related documents and procedures, are based on the principle that they should state what should be done to ensure that specified work or activity may be carried out without Danger so far as is reasonably practicable. The Dangers that can arise are two-fold:

- i. inherent **Dangers** from distribution **Systems, Plant** and **Apparatus**, which are covered by the Operational Safety Rules (**OSR**); and
- ii. general **Dangers** associated with the work as it proceeds including, in addition to the work process, **Dangers** from access and egress, the place of work and the working environment (these **Dangers** may be of a different kind, and under different control, from the inherent **Dangers** in (i) above and may not be specifically covered by the **OSR**).

P2

In the implementation of the **OSR**, related documents and procedures, specified methods of work, and other forms of local instruction, management **Shall** allocate responsibility for the achievement of health and safety from the inherent **Dangers** mentioned in (i) above during the various stages of work or activity. Management **Shall** also carry out a suitable and sufficient risk assessment, issue instructions and allocate responsibility for dealing with the general **Dangers** mentioned in (ii) above where such **Dangers** are not already specifically covered in these **OSR** or associated **Approved** Procedures or Codes of Practice.

P3

It is **SSEN-D** policy that the persons in charge of the various stages of the work or activity **Shall** have the appropriate competence and written authority and **Shall** understand the **OSR**, related documents and procedures, the methods of work and any local instructions. Such **Persons Shall** understand the **Dangers** that might arise and the precautions to be taken over the whole period of the work or activity. **SSEN-D** policy requires that all persons at work are adequately instructed and supervised and are competent to avoid **Danger**. It is also **SSEN-D** policy that the relevant legal requirements, the **OSR** and other required health and safety precautions are observed at all times. Reminder – safety rule 1.9 states that ignorance of rules and procedures can't be accepted as an excuse for neglect of duties.

1. GENERAL PROVISIONS

1.1 SCOPE AND APPLICATION OF THE OPERATIONAL SAFETY RULES

These **SSEN-D OSR** apply to distribution **Systems** up to and including 132kV and to associated **Plant** and **Apparatus** under the ownership or control of **SSEN-D** under whose authority they have been issued. These **Shall** normally be the only Rules applicable to such **Systems**, and **Shall** be applied in accordance with management instructions, together with related documents and **Approved** procedures, for the whole course of the work for which they are intended.

1.2 OTHER SAFETY RULES, RELATED DOCUMENTS AND PROCEDURES

In addition, or as an alternative, to the application of these **OSR** and related documents and procedures, other rules, documents and procedures issued by **SSEN-D**, or by other authorities, **Shall** be complied with in accordance with management instructions. Whereas the Appendices to these **OSR** are not, in themselves, individual Safety Rules, they **Shall** be read in conjunction with the Rules to which they relate. As such, the Appendices form important supporting information for the implementation of the **OSR**.

It Shall be appreciated that SSEN-D Systems have interfaces with other Systems, e.g. Customer owned Systems, Independent Distribution Network Operator Systems, Transmission Network Operator Systems, other Distribution Network Operator Systems, etc. It is common and possible for interfacing Systems to have different ownership and therefore, each operator Shall ensure effective communication, collaboration, and coordination of interface activities to help avoid Danger.

Where an appropriate written agreement exists between **SSEN-D** and a Third-Party, the employees of that Third-Party may carry out work and operate on the Distribution **Systems** under the control and ownership of **SSEN-D**. The employees of the Third-Party may carry out work and operate in accordance with other rules and procedures, provided that this approach complies fully with the detail of the written agreement between **SSEN-D** and the Third-Party.

Safety precautions required across control/ ownership boundaries **Shall** be carried out and documented in accordance with **Approved** procedures.

Reminder – when operating and/or working on the System, all Persons should have their Authorisation Certificate and Operational Safety Rule book with them.

Such procedures **Shall** be agreed between the controller/ owner of the other **System** and **SSEN-D** and **Shall** be made known to the **Persons** concerned. In all cases these **OSR** and related documents and procedures **Shall** be used as a guide to safe working.

1.3 INFORMATION, INSTRUCTION AND TRAINING

Arrangements Shall be made by SSEN-D to ensure:

- (i) That all employees concerned are adequately informed as to; -
 - the risks to their health and safety as identified by risk assessment;
 - the preventative and protective measures to be taken;
 - the procedures to be followed in the event of serious and imminent **Danger**; and
 - the risks arising from the activities of any other employer and/or employee.
- (ii) That adequate levels of supervision of its employees and those under its control are provided.
- (iii) That all employees concerned are adequately informed and instructed as to the Systems, Plant and Apparatus which are affected by a particular operation or work (whether or not they are owned or operated by SSEN-D) and which legal requirements, Safety Rules, related documents and procedures Shall apply.
- (iv) That other persons who are not employees, but who are carrying out work or operations on behalf of SSEN-D and might be exposed to Danger during their operations or work, also receive adequate information, training, instruction and supervision.
- That the capabilities of employees are taken into account in allocating tasks.
- (vi) That employees are provided with adequate health and safety training and re-training.

The Designated Engineer, or their nominated deputy, must assess and approve all such special procedures before they are used.

SSEN Distribution Operational Safety Manual Section 3.3 for Erroneous Operations.

SSEN Distribution Operational Safety Manual Section 12.9 for Asset Failures.

SSEN Distribution Operational Safety Manual Section 2.5 for System Reporting Requirements.

If needed, further guidance can be obtained from the SSEN Distribution SHE team.

Page 12 of 158

1.4 ISSUE OF OPERATIONAL SAFETY RULES

A copy of these **OSR**, and as appropriate, related documents and procedures **Shall** be issued to such employees of **SSEN-D** and such other persons as the **Designated Engineer** may determine. Such employees and other persons **Shall** keep them in good condition and have them available for reference as necessary when work is being carried out under these **OSR**.

1.5 SPECIAL PROCEDURES

Work on or testing of **Apparatus**, **Conductors** or **Plant** to which these **OSR** cannot be applied, or for special reasons should not be applied, **Shall** be carried out in accordance with an **Approved** procedure. Such a procedure **Shall** ensure that the safety requirements of these **OSR** are satisfied in some other way.

1.6 VARIATION OF MODEL DISTRIBUTION SAFETY RULES

Individual Companies may vary the MDSR as required to suit their individual circumstances. Such variations **Shall** be **Approved** by the individual company's **Designated Engineer**.

1.7 OBJECTIONS

When any person receives instructions regarding the operation of, or work on **SSEN-D System**, and associated **Plant** and **Apparatus**, they **Shall** report any objections on safety grounds to the carrying out of such instructions to the **Persons** issuing them, who **Shall** then have the matter investigated and, if necessary, referred to a higher authority for a decision before proceeding.

1.8 REPORTING OF ACCIDENTS AND DANGEROUS OCCURRENCES

Persons Shall comply with any **SSEN-D** procedures for the statutory reporting of accidents and dangerous occurrences. In addition, all electrical accidents, electrical dangerous occurrences and such other accidents and dangerous occurrences involving **SSEN-D** High Voltage Systems or associated Plant and Apparatus, Shall be reported immediately to the appropriate Control Engineer in accordance with Approved procedures. In the case of accidents and dangerous occurrences involving Low Voltage Systems or associated Plant or Apparatus, these Shall be reported immediately in accordance with Approved procedures.

Please see arrangements relating to Personal Protective Equipment in the SSEN Distribution Occupational Safety Manual.

If you're not sure, stop and ask for help.

1.9 DUTIES

SSEN-D as an employer has a duty to comply with the provisions of the Health and Safety at Work. Act 1974, the Electricity at Work Regulations 1989, and other relevant statutory provisions. Additionally, authoritative guidance is available from the Health and Safety Executive and other sources. **SSEN-D** employees and contracted persons also have a duty to comply with the provisions of the Health and Safety at Work. Act 1974, the Electricity at Work Regulations 1989 and with other relevant statutory provisions.

In addition to these statutory duties and any other duties separately allocated to them, all **Persons** who may be concerned with the operation of, or work upon, distribution and transmission **Systems** and associated **Plant** and **Apparatus Shall** be conversant with, and comply with, those **OSR** relevant to their duties and related documents and procedures. Ignorance of legal requirements, or of Safety Rules and related documents and procedures, **Shall** not be accepted as an excuse for neglect of such duties.

If any **Person** has any doubt as to any of these duties, they **Shall** report the matter to a higher authority for advice before proceeding with work, i.e. if you are not sure, stop and ask for help.

1.10 USE AND WEARING OF SAFETY EQUIPMENT AND PROTECTIVE CLOTHING

Where any work under these **OSR** and related documents and procedures takes place, appropriate safety equipment and protective clothing of an **Approved** type **Shall** be issued and used in accordance with management instructions. At all times employees are expected to wear sensible clothing and footwear having regard to the work being carried out.

1.11 TREATMENT FOR ELECTRIC SHOCK

All persons who may be concerned with the operation of, or work upon, the **SSEN-D Systems**, and associated **Plant** and **Apparatus**, **Shall** be trained in and be conversant with the treatment of electric shock. Please also note that the rear-page of these **SSEN-D OSR** contains summary guidance for **Persons** on treatment of electric shock.

SSEN Distribution Operational Safety Rules 2022

If it's not safe, we don't do it.

Page 16 of 158

2. DEFINITIONS

ADDITIONAL EARTH

Earthing equipment of **Approved** type which is applied after the issue of a **Safety Document** (for example an **Earth** applied at a point of work).

APPARATUS

Any item of electrical machinery or equipment in which **Conductors** are used, or supported, or of which they form part.

APPROVED

Sanctioned by the **Designated Engineer** in order to satisfy, in a specified manner, the requirements of any or all of these **OSR**.

AUTHORISED PERSON

An experienced **Competent Person** with appropriate technical knowledge and ability who has been appointed in writing by **SSEN-D** to carry out specified duties which may include authority to issue and cancel **Limitations-of-Access** and/or to receive **Sanctions-for-Test**.

CONDUCTOR

An electrical conductor arranged to be electrically connected to a System.

COMPETENT PERSON

A **Person** recognised by **SSEN-D** as having sufficient technical knowledge and experience to enable them to avoid **Danger** and who may be nominated to receive and clear specified **Safety Documents** and **Shall** be appointed in writing.

CIRCUIT MAIN EARTH

Earthing equipment of **Approved** type applied before the issue of, and at a position recorded in a **Safety Document**.

CAUTION NOTICE

A notice in **Approved** form prohibiting unauthorised interference, with such additional **Approved** words as **SSEN-D** may determine.

DANGER

A risk to health or of bodily injury.

SSEN Distribution Operational Safety Manual Section 2 – System Control Procedures.

Please see the SSEN Distribution Approved Tools and Equipment list and catalogue (available via SSEN Distribution intranet pages) for Approved earthing leads and equipment.

SSEN Distribution Operational Safety Manual Section 2.11 – Transfer of System Control Responsibilities.

Page 18 of 158

DANGER NOTICE

A notice in **Approved** form reading "**Danger**" with such additional **Approved** words as **SSEN-D** may determine.

DESIGNATED ENGINEER

The person appointed by **SSEN-D** to be responsible for the application of these **OSR**.

DEAD

At or about zero voltage and disconnected from any Live System.

DISTRIBUTION CONTROL ENGINEER

In the case of a centrally controlled **System** the **Control Engineer** at an **SSEN-D** Control Centre.

DISTRIBUTED ENERGY RESOURCES

Small scale electricity generation, flexible demand, or storage units (typically in the range of 3kW to 50mW) located within the electricity distribution network and connected to the **System**. These can be owned and operated by licence holders or Third-Parties and are connected to the **System** through agreement with the distribution **System** licence holder.

EARTH

The conductive mass of the **Earth**, whose electric potential at any point is conventionally taken as zero.

EARTHED

Connected to **Earth** through switchgear with an adequately rated earthing capacity, or by **Approved** earthing equipment.

FIELD CONTROL ENGINEER

In the case of a locally controlled **System** the engineer specifically deputed to exercise the function of control of such a **System**, in accordance with an **Approved** procedure.

GENERAL SAFETY

The control and management of risks posed by hazards in the working environment which are not covered by the **OSR**.

SSEN Distribution Operational Safety Manual Section 15 – High Voltage Live Line Work.

HIGH VOLTAGE (HV)

A voltage exceeding 1000 Volts AC or 1500 Volts DC.

HIGH VOLTAGE LIVE LINE WORK

Work in an **Approved** manner on the **Conductors** or **Apparatus** of a **High Voltage** overhead line with the **Conductors Live**.

IMMEDIATE SUPERVISION

Supervision by a **Person** (having adequate technical knowledge, experience and competence) who is continuously available at the location where work or testing is in progress, and who attends the work area as is necessary for the safe performance of the work or testing.

ISOLATED

Disconnected from associated **Plant**, **Apparatus** and **Conductors** by an **Isolating Device** in the isolating position, or by adequate physical separation, or sufficient gap.

ISOLATING DEVICE

A device for rendering **Plant** and **Apparatus Isolated**.

KEY SAFE

A device of an **Approved** type for the secure retention of keys.

LIMITATION-OF-ACCESS

A **Safety Document** defined within an **Approved** procedure which defines the limits and nature of work which may becarried out when verbal instructions are not considered sufficient for that purpose, and where a **Permit-to-Work** or **Sanction-for-Test** is not applicable.

LIVE

Electrically charged.

LOW VOLTAGE (LV)

A voltage not exceeding 1000 Volts AC or 1500 Volts DC.

OSR

These Distribution Operational Safety Rules put in place and managed by **SSEN-D**.



Have you registered?

Page 22 of 158

PERMIT-TO-WORK

A **Safety Document** defined within an **Approved** procedure which specifies the **High Voltage Apparatus** which has been made safe to work on andthe work which is to be carried out.

PERSONAL SUPERVISION

Supervision by a **Person** (having adequate technical knowledge, experience and competence) such that they are at all times during the course of the work or testing, continuously observing and in the presence of the person(s) being supervised, with the ability and competence to directly intervene.

Note: - **Supervision** at ground level provided for persons(s) positioned at height is considered to be **Personal Supervision** when the supervisor at ground level maintains verbal and visual communication with the person(s) being supervised.

PLANT

Mechanical plant including all machinery and equipment not elsewhere defined as Apparatus.

SAFETY DISTANCE

The distance from the nearest **High Voltage** exposed **Conductor** not **Earthed** or from an insulator supporting a **High Voltage Conductor**, which must be maintained to avoid **Danger.**

SAFETY LOCK

A lock used exclusively for **Approved** purposes (such as for locking-off the points at which the circuit can be energised) that lock being different from all other standard locks used on **Systems**.

SANCTION-FOR-TEST

A Safety Document defined within an Approved procedure which specifies the High Voltage Apparatus which has been made safe for the testing described in the Safety Document to proceed and the conditions under which the testing is carried out.

SENIOR AUTHORISED PERSON

An **Authorised Person** who has been appointed in writing by **SSEN-D** to carry out specified duties, including the issue and cancellation of **Safety Documents**.

SSEN Distribution Operational Safety Rules 2022

We take care of ourselves and each other.

Page 24 of 158

SHALL

Where '**Shall**' is used in these **OSR** with no qualification, this indicates a mandatory requirement with no discretion permitted and no judgement to be made.

This can be qualified by either 'where practicable' or 'reasonably practicable'.

Where 'Shall' is qualified only by the word 'practicable' a slightly less strict standard is imposed. It means that where it is possible to achieve in the light of current knowledge and invention, however bearing in mind the hazards associated with the work to be undertaken, then the requirement must be met. One is not allowed to avoid the requirement on the grounds of difficulty, inconvenience, or cost.

When '**Shall**, where reasonably practicable' is used to qualify a requirement then a judgement must be made as to what is reasonable, taking into account the magnitude of the risk on one hand and the cost, time and trouble, or effort necessary for averting the risk on the other hand.

SSEN-D

Scottish and Southern Electricity Networks Distribution companies (sometimes referred to as SSEN Distribution).

SWITCHING

The operation of circuit-breakers, isolators, disconnectors, fuses or other methods of making or breaking an electrical circuit and/or the application and removal of **Circuit Main Earths**.

SYSTEM

An electrical system in which **Conductors** and **Apparatus** are electrically connected to a common source of supply.

WORKING AND ACCESS CLEARANCE

The distance to be maintained from the nearest Live exposed High Voltage Conductor as specified in these OSR to ensure observance of the Safety Distance for work on or near Systems.

WORKING PARTY

Either the persons under the **Supervision** of a **Competent or Authorised Person** (who **Shall** themselves be a member of the working party) or a **Competent or Authorised Person** when working alone.

Please see arrangements relating to Confined Spaces in the SSEN Distribution Occupational Safety Manual.

If you're not sure, stop and ask for help.

3. GENERAL SAFETY PRECAUTIONS

3.1 GENERAL SAFETY

3.1.1 In addition to all other requirements specified in these OSR the safety of persons at work Shall also be achieved by maintaining at all times General Safety at and in the vicinity of the place of work. Before work or testing commences the Person in charge of the Working Party Shall ensure that safety precautions are taken to establish General Safety at and in the vicinity of the workplace. This Person Shall ensure that at all times during the work or testing that General Safety arrangements are maintained and that other work areas are not adversely affected by the activities for Which they are responsible. The discharging of responsibilities for General Safety will be achieved as part of the normal pattern of management delegation and control by ensuring that all activities are carried out in accordance with appropriate instructions and guidance.

3.2 ACCESS TO AND WORK IN OPERATIONAL PREMISES, UNDERGROUND CHAMBERS, CONFINED SPACES AND VESSELS CONTAINING OIL OR OTHER FLAMMABLE OR TOXIC SUBSTANCES

- 3.2.1 No person Shall, without proper authority, enter or have access to any operational premises such as any control room, substation, switching station or underground chamber belonging to, or wholly under the control of SSEN-D.
- 3.2.2 Access to confined spaces such as underground chambers, cable tunnels and indoor substations with restricted access or egress Shall be gained in accordance with an Approved procedure.
- 3.2.3 Access to vessels recently emptied of flammable or toxic substances, Shall only be allowed in accordance with an Approved procedure which includes provision to expel all dangerous vapours and substances.
- 3.2.4 Work involving the application of heat or the use of exposed flames, in the vicinity of open vessels containing or having recently contained flammable substances, **Shall** be prohibited until all practicable steps have been taken, in accordance with an **Approved** procedure, to prevent **Danger**.

SSEN Distribution Operational Safety Manual Section 6.1 – Access to Substations and Switching Stations.

3.3 ACCESS TO AND WORK IN FIRE PROTECTED AREAS

3.3.1 AUTOMATIC CONTROL

Unless alternative **Approved** procedures apply because of special circumstances, then before access to, work, or other activities are carried out in any enclosure protected by automatic fire extinguishing equipment:

- (a) the automatic control Shall be rendered inoperative and the equipment left on manual control and locked where practicable. A Caution Notice Shall be attached;
- (b) precautions taken to render the automatic control inoperative and the conditions under which it may be restored Shall be noted on any Safety Document or written instruction issued for access, work or other activity in the protected enclosure; and
- (c) the automatic control Shall be restored immediately after the persons engaged on the work or other activity have withdrawn from the protected enclosure.

3.3.2 PORTABLE FIRE EXTINGUISHERS

Only **Approved** portable fire extinguishers **Shall** be available and used in the vicinity of **Live Apparatus** and **Conductors**. In the handling of fire extinguishers, the appropriate **Safety Distances** specified in Rule 4.4 **Shall** be maintained. After the discharge of portable fire extinguishers in an enclosed space, personnel **Shall** leave the space until the precautions set out in Rule 3.2.3 have been taken.

3.3.3 GENERAL

After any explosion or fire, or after the discharge of fire extinguishers in an enclosed space, either the space **Shall** be adequately ventilated before entry of personnel or **Approved** breathing apparatus and, where necessary, **Approved** safety harnesses **Shall** be worn by persons specially trained in their use. Such breathing apparatus and safety harnesses **Shall** be worn in any case of doubt.

Please see the SSEN Occupational Safety Manual and arrangements for working at height on overhaed lines; and

SSEN Distribution Operational Safety Manual Section 7 – Access and Work on High Voltage Overhead Lines.

If you're not sure, stop and ask for help.

SSEN Distribution Operational Safety Manual Section 7.1 – Management of Work and Access to Poles.

SSEN Distribution Operational Safety Manual Section 7.2 – Management of Work and Access to Towers.

SSEN Distribution Operational Safety Manual Section 7 – Access and Work on High Voltage Overhead Lines.

SSEN OSM Section 6.2 – Management and Demarcation of Work or Testing in Substations with Exposed Busbar or Gas Insulated Apparatus.

3.4 ACCESS TO OR WORKING ON POLES, TOWERS AND HIGH STRUCTURES

- 3.4.1 Before any pole is accessed or worked on, it Shall be tested in an Approved manner. No pole badly impaired by decay or damage or whose stability is in doubt Shall be accessed or worked on until it has been supported by Approved means. The pole Shall then either be climbed by only one person at a time or access to the top of such pole Shall be by Approved means independent of the pole.
- 3.4.2 All **Persons** gaining access to and during work on towers, poles and high structures **Shall** make proper use of **Approved** safety equipment and **Shall** be in visual range of another **Person**, in a position to immediately render effective assistance, where necessary. All **Persons** concerned **Shall** be fully conversant with **Approved** rescue procedures. Unaccompanied access is allowed for **Switching** or testing when it is of limited duration and is covered by an **Approved** procedure.
- 3.4.3 Gates and devices to prevent climbing of towers, gantries and structures that support **High Voltage Conductors Shall** always be kept secured in an **Approved** manner and access **Shall** be controlled by an **Authorised Person** or **Competent Person** in receipt of an appropriate **Safety Document** or to an **Approved** procedure.

3.5 ACCESS TO HIGH VOLTAGE APPARATUS AND CONDUCTORS

3.5.1 HIGH VOLTAGE STRUCTURES AND OUTDOOR COMPOUNDS

Guards on access ladders, barriers, or doors and gates on or in outdoor compounds preventing access to Live High Voltage Conductors Shall be kept secured in an Approved manner and access Shall be in accordance with Approved procedures.

3.5.2 HIGH VOLTAGE CHAMBERS, CUBICLES AND CELLS

Barriers, doors or gates preventing access to totally enclosed chambers, cubicles and cells containing Live High Voltage Conductors Shall, where the facility exists, be kept locked and the keys Shall be accessible only to an Authorised Person.

SSEN Distribution Operational Safety Manual Section 4.2 – High Voltage Switching and Earthing.

SSEN Distribution Operational Safety Manual Section 4.1 – Network Operating Procedures for Operators.

SSEN Distribution Operational Safety Manual Section 2.1 – System Operating Procedures for Control Engineers.

Page 32 of 158

3.5.3 SPOUT SHUTTERS ON HIGH VOLTAGE SWITCHGEAR

All spout shutters not required for immediate work or operation **Shall**, if the spouts are not otherwise made inaccessible, be locked shut and the keys **Shall** only be accessible to an **Authorised Person**.

3.6 HIGH VOLTAGE SWITCHING

- 3.6.1 No High Voltage Switching Shall be carried out other than by an Authorised Person or by a Competent Person acting under the Personal Supervision of an Authorised Person. No such Switching Shall be carried out without the authority of the appropriate Control Engineer, except in cases of emergency, or other Approved cases, which may include Switching by remote control by a Control Engineer.
- 3.6.2 When a Control Engineer gives authority for High Voltage Switching to be carried out they Shall communicate directly with the Person who is to carry out the Switching. Where, for special reasons, direct communication is not possible, an Approved procedure Shall be followed. Any Person who is to carry out High Voltage Switching Shall have an Approved record of the Switching instruction available at the point of Switching.
- 3.6.3 Before any High Voltage Switching is carried out on any System which might affect another System, the Control Engineer authorising the Switching Shall communicate with the Control Engineer of the other System and the Switching Shall be agreed between them, and recorded by all Control Engineers concerned.
- 3.6.4 Where High Voltage Switching is to be carried out for the purpose of issuing a Safety Document and there are two or more control functions involved then, in the absence of a standing agreement for such matters, the Control Engineers concerned Shall agree on the Person who Shall be in control of the part of the System in the Isolated zone, and who Shall be responsible for giving consent to the issuing of a Safety Document. Such agreement between the Control Engineers Shall be recorded by each Control Engineer.
- 3.6.5 Where there are special requirements to be complied with before, during or after High Voltage Switching operations, Approved procedures Shall apply and special provision Shall be made to ensure that the Control Engineers, the operators and others affected are aware of their responsibilities.

SSEN Distribution Operational Safety Manual Section 2.7 – Switching Schedules.

Please see the SSEN Distribution Approved Tools and Equipment list and catalogue (available via SSEN Distribution intranet pages) for Approved equipment such as umbilical devices.

In terms of Approved Procedures, please reference SSEN Distribution Operational Safety Manual Section 4.2 – High Voltage Switching and Earthing.

If you're not sure, stop and ask for help.

Please see arrangements relating to Personal Protective Equipment in the SSEN Distribution Occupational Safety Manual.

If you're not sure, stop and ask for help.

3.6.6 High Voltage Switching with the Control Engineer's authority Shall be carried out without unnecessary delay. Completed Switching operations Shall be confirmed to the Control Engineer as agreed and without unnecessary delay, by an Approved means.

Emergency **Switching** (in accordance with Rule 3.6.1) **Shall** be reported to the **Distribution Control Engineer** without unnecessary delay. The circumstances necessitating such **Switching Shall** be explained at that time.

- **3.6.7** All switchgear operations **Shall**, so far as reasonably practicable, be planned and completed in accordance with the following hierarchy:
 - (i) Remotely via remote control facilities;
 - Remotely on site via control panels in a different room to the switchgear being operated;
 - (iii) Remotely via a control panel in the same room as the switchgear being operated;
 - (iv) Remotely via an Approved umbilical device or similar; or
 - (v) Via the operating facilities on the switchgear.

Switchgear (including associated equipment) which is to be operated locally on site **Shall** be visually inspected immediately before any **Switching** operation to check its condition is satisfactory. The switch to be operated **Shall** be visually checked to ensure that it is in the expected position prior to operating.

Following the intended operation, switchgear **Shall** be visually checked to ensure the anticipated position has been achieved and it has operated fully and correctly.

When switchgear shows any signs of distress, its condition **Shall** be reported immediately to the **Control Engineer** and it **Shall** be examined before a decision is made about further operation.

- 3.6.8 When operating switchgear mounted on a pole or other structure from ground level, the operator **Shall** wear **Approved** Personal Protective Equipment (PPE) and use such other equipment as may be **Approved**.
- **3.6.9** It is forbidden to undertake **Switching** by signal or pre-arranged understanding after an agreed interval of time.

SSEN Distribution Operational Safety Manual Section 2.7 – Switching Schedules.

Please see the SSEN Distribution Approved Tools and Equipment list and catalogue (available via SSEN Distribution intranet pages) for Approved equipment such as Voltage test devices.

In terms of Approved Procedures, please reference:

- SSEN Distribution Operational Safety Manual Section 4.2 – High Voltage Switching and Earthing; and
- SSEN Distribution Operational Safety Manual Section 4.3 – Low Voltage Switching and Earthing.

SSEN Distribution Operational Safety Manual Section 8.1 – Access and Work on High Voltage Underground Cables.

SSEN Distribution Operational Safety Manual Section 7 – Access and Work on High Voltage Overhead Lines.

3.7 RECORDS

3.7.1 MESSAGES

Messages by telephone or otherwise, relating to the operation of any **High Voltage System**, **Shall** be recorded by **Approved** means. Every such message **Shall** be read back to the sender to ensure that it has been accurately received, or confirmed back to the sender to ensure that it has been accurately received in accordance with an **Approved** procedure.

3.7.2 RECORDING OF SWITCHING

The **Control Engineer Shall** ensure that a record is made of the time and particulars of all **High Voltage Switching** including any carried out by the **Control Engineer** by remote control.

3.8 FAILURE OF SUPPLY

A failure of supply, from whatever cause, to or from any part of the **High Voltage System Shall** be immediately reported to the **Distribution Control Engineer**. During failures of supply all **Apparatus** and **Conductors Shall** be regarded as being **Live** unless **Isolated** and proved **Dead** by **Approved** means.

3.9 USE OF VOLTAGE TEST DEVICES

Where voltage testing devices are used they **Shall** be of **Approved** type and such use **Shall** be in accordance with **Approved** procedures. Such devices **Shall** be tested in an **Approved** manner immediately before and after use or, where this is not reasonably practicable; they **Shall** be tested in accordance with **Approved** procedures.

3.10 EXCAVATION NEAR LIVE CABLES

All damaged cables or cables with exposed **Conductors Shall** be treated as **Live** until identified and proved **Dead** by an **Approved** procedure. When excavation work is carried out in proximity to **Live** cables by **SSEN-D** or its contractors, the work **Shall** be done in accordance with an **Approved** procedure.

3.11 USE OF MOBILE PLANT AND EQUIPMENT NEAR OVERHEAD LINES

When **SSEN-D** or its Contractors are working adjacent to overhead lines with mobile **Plant** and equipment which is capable of reaching within the **Safety Distance** of a **Live High Voltage Conductor**, or touching a **Live LV Conductor** the work **Shall** be done in accordance with an **Approved** procedure.

SSEN Distribution Operational Safety Manual Section 5.2 – Use and Completion of Operational Documents.

4. SAFETY PRECAUTIONS FOR WORK ON OR NEAR HIGH VOLTAGE SYSTEMS

4.1 GENERAL REQUIREMENTS

All **High Voltage Apparatus** and **Conductors**, including those that are damaged or have faulted, **Shall** be treated as **Live** unless they have been made safe in accordance with Rule 4.1.1.

- 4.1.1 Subject to the exceptions stated below and those expressly permitted by individual Rules, no person Shall undertake any repair, maintenance, cleaning, alteration or such work, on or within the Safety Distance of an exposed Conductor or on any part of a High Voltage System unless such parts of the System are:
 - (a) **Dead**;
 - (b) Isolated and all practicable steps taken to lock off from all points of supply, including voltage and auxiliary transformers, common neutral earthing equipment and other sources from which the Apparatus and Conductors may become Live, and Caution Notices fixed at all points of isolation;
 - (c) connected to Earth by Approved means at all points of disconnection of High Voltage supply from the System or between such points and the point(s) of work;
 - (d) screened where necessary to prevent Danger and Danger Notices attached to Apparatus containing Live Conductors and attached adjacent to other Live Conductors;
 - (e) identified at the point of work by **Approved** means; and
 - (f) released for work and the measures taken under this Rule are formally communicated to the Working Party, using an Approved procedure which involves the issue of appropriate Safety Documents which Shall not be issued unless the issuer and the recipient are fully conversant with the precise parts of the Systems, Apparatus and Conductors to be worked upon, the nature and also the extent of the work to be done and the safety precautions to be taken.

It is the duty of the **Person** issuing the appropriate **Safety Document** to ensure compliance with the foregoing provisions in the correct sequence.

These exceptions Shall only be used at the discretion of a Senior Authorised Person, and in accordance with an Approved Procedure.

If you're not sure, stop and ask for help.

SSEN Distribution Operational Safety Manual Section 6.3 – Work on HV Plant and Apparatus.

SSEN Distribution Operational Safety Manual Section 4.2 – High Voltage Switching and Earthing.

EXCEPTIONS (to 4.1.1)

- Work such as cleaning and painting of Earthed metal enclosures, connections or disconnections of circuits to or from Live High Voltage Systems, Live line testing and Live insulator washing may be carried out but only in accordance with Approved procedures;
- (ii) High Voltage Live Line Work on High Voltage overhead lines may be carried out but only in accordance with Section 6 of these OSR;
- (iii) Where the design of Apparatus precludes strict compliance with all the requirements of Rule 4.1.1 the work Shall be carried out in accordance with an Approved procedure or to the specific written instruction of a Senior Authorised Person, and after agreement with the Distribution Control Engineer, to ensure that safety is achieved in another way. Such work Shall be carried out under the Personal Supervision of a Senior Authorised Person;
- (iv) Where work will proceed at a single point on an overhead line, and where that work will not interfere with the continuity of the **Conductors**, one **Circuit Main Earth** applied at the point of work is acceptable; and
- (v) Where work is carried out on a High Voltage overhead System and where it is not reasonably practicable to isolate all connected consumers in accordance with Rule 4.1.1(b), an Additional Earth Shall be provided and maintained between that consumer and the point of work unless a Circuit Main Earth is provided in that position.

4.2 ISOLATION OF APPARATUS AND CONDUCTORS

4.2.1 No isolation or reconnection of High Voltage Apparatus or Conductors Shall be initiated except with the sanction of the Control Engineer.

4.2.2 SAFETY LOCKS

- (a) Where a locking facility exists Safety Locks Shall be used to lock open all switchgear at points where the circuit on which work is to be carried out could be energised. The keys for such locks Shall be kept in a Key Safe, in the possession of a Senior Authorised Person or in accordance with an Approved procedure.
- (b) Details of the isolation referred to in Rule 4.2.1 and deposit of Safety Lock keys associated with the isolation, Shall be recorded at centres specified in Approved procedures.

SSEN Distribution Operational Safety Manual Section 4.2 – High Voltage Switching and Earthing.

Please see the SSEN Distribution Approved Tools and Equipment list and catalogue (available via SSEN Distribution intranet pages) for Approved equipment such as Voltage test devices and earthing equipment.

In terms of Approved Procedures, please reference SSEN Distribution Operational Safety Manual Section 4.2 – High Voltage Switching and Earthing.

4.2.3 FUSES OR LINKS

When the circuit on which work is to be carried out is controlled only by fuses or links, the fuses, links (and carriers) **Shall** be removed and kept in a safe place which may include custody by the **Person** responsible for issuing the **Safety Document**. Where the removal could increase the risk of third-party interference or inadvertent contact with **Live Conductors**, consideration **Shall** be given to insertion of **Approved** blanking devices. Where such removal is not practicable, **Approved** procedures to ensure safety **Shall** be followed.

4.2.4 CAUTION NOTICES

Caution Notices Shall be fixed at all points of isolation and secured with a **Safety Lock** where reasonably practicable.

4.3 EARTHING

- 4.3.1 When High Voltage Apparatus and Conductors are to be discharged and Earthed in accordance with Rule 4.1.1(c) it Shall be done:
 - (a) where reasonably practicable by the use of a circuit-breaker or earthing switch provided for the purpose to make the earthing connection. When the circuit-breaker is used, the trip feature Shall normally be rendered inoperative before closing, unless this is not practicable when it Shall be done afterwards. After closing, the circuit-breaker or earthing switch Shall be locked in the Earthed position, so that it remains inoperative while it is the Circuit Main Earth; or
 - (b) where (a) is not reasonably practicable or not applicable, the High Voltage Apparatus and Conductors Shall be checked by means of an Approved voltage testing device or other Approved means to verify that they are not Live, and may then be discharged and Earthed by an earthing lead applied by means of an Approved earthing pole or other Approved appliance.
 - (c) In addition to the requirements in sections (a) and (b) above the first Earth applied to, and the last Earth removed from a circuit Shall where reasonably practicable be achieved using a circuit-breaker or earthing switch provided for that purpose. It is not normally considered reasonably practicable to disrupt electricity supplies in order to meet these requirements.

Please see the SSEN Distribution Approved Tools and Equipment list and catalogue (available via SSEN Distribution intranet pages) for Approved earthing equipment.

Please see the SSEN Distribution Approved Tools and Equipment list and catalogue (available via SSEN Distribution intranet pages) for Approved equipment such as Voltage test devices and earthing equipment.

In terms of Approved Procedures, please reference SSEN Distribution Operational Safety Manual Section 4.2 – High Voltage Switching and Earthing.

4.3.2 EARTHING LEADS AND CONNECTIONS

Earthing leads and associated clamps **Shall** be of an **Approved** type and of adequate capacity for the duty at the point of application. They **Shall** be adequately maintained and always examined immediately prior to use.

4.3.3 PROCEDURE FOR THE USE OF EARTHING LEADS

Subject to Rule 4.3.1 the general procedure to be followed when using earthing leads **Shall** be as follows:

- the circuit Shall be verified that it is not Live and, where practicable, checked by means of an Approved voltage testing device or other Approved means;
- (b) earthing leads Shall be connected to Earth before being connected to the phase Conductors. They Shall be connected to the phases by means of an Approved earthing pole or other Approved appliance. Care Shall be taken to ensure that good contact is made and that earthing leads are clearly visible;
- (c) all phases **Shall** be **Earthed**, even if work is to be carried out only on one phase;
- (d) earthing leads Shall not be applied in any cell or compartment in which there is any exposed metal Live at High Voltage which might be a source of Danger. Earthing leads Shall be applied in such a manner that they remain clearly visible so far as reasonably practicable;
- (e) when earthing leads are being removed each one Shall be disconnected from its phase Conductor by means of an Approved earthing pole or other Approved appliance before it is removed from the Earth connection; and
- (f) for the purpose of earthing on spout contacts of metal-enclosed switchgear, only Approved appliances Shall be used. The insertion of the hand or any tool into contact spouts for this purpose is forbidden.

Reminder – safety rule 1.7 can be used for objections on safety grounds.

4.3.4 CIRCUIT MAIN EARTHS

(a) Operation:

No **High Voltage** earthing switch **Shall** be operated or **Circuit Main Earth** connected or disconnected except with the consent of the **Control Engineer** (or under the terms of a **Sanction-for-Test** or under 5.1.2 or 5.5.4(i)). Where a locking facility exists, **Circuit Main Earths Shall** be secured by an **Approved** lock.

(b) Recording of Circuit Main Earths:

Completed earthing operations **Shall** be confirmed to the **Control Engineer** as agreed and without unnecessary delay. The location of each **Circuit Main Earth Shall** be recorded on the **Safety Document**.

(c) The Control Engineer Shall record in their log the time of application and the location of each Circuit Main Earth connection and the time of its removal except under the terms of a Sanction-for-Test or Rules 5.1.2 or 5.5.4 (i).

4.3.5 ADDITIONAL EARTHS

- (a) Additional Earths applied after the issue of a Permit-to-Work or Sanction-for-Test may only be attached or removed by the recipient of the Safety Document or a Competent Person under their Personal Supervision.
- (b) When the recipient of a Permit-to-Work clears and returns the Permit-to-Work to a Senior Authorised Person the recipient clearing the Permit-to-Work Shall ensure that the Senior Authorised Person is aware of the position of any Additional Earths that have not been removed.

Note: - Safety Distances for 275kV and 400kV provided for reference purposes.

Please see reference information relating to HVDC systems within section 16 of the SSEN Distribution Operational Safety Manual.

4.4 APPROACH TO EXPOSED LIVE HIGH VOLTAGE CONDUCTORS OR INSULATORS SUPPORTING THEM

4.4.1 SAFETY DISTANCES

- (a) The Safety Distances (designated 'X' in Table 1 and Diagram 1) Shall be maintained at the respective System voltages between any part of a person or object and the nearest exposed Live High Voltage Conductor.
- (b) A distance of 300mm Shall also be maintained, at all System voltages, from the portion of insulators supporting Live High Voltage Conductors which is outside the appropriate Safety Distance from the Conductors.

Nominal System Voltage		Safety Distance 'X'	
Up to and including		33kV	0.8 m
Exceeding 33kV	but not exceeding	66kV	1.0 m
Exceeding 66kV	but not exceeding	132kV	1.4 m
Exceeding 132kV	but not exceeding	275kV	2.4 m
Exceeding 275kV	but not exceeding	400kV	3.1 m

Table 1 - Safety Distances

NOTE: **Safety Distances** for **High Voltage** Direct Current **Systems** and **High Voltage** traction load supplies can be different to the distances provided above. Where applicable, **Electricity Companies Shall** provide these details in an **Approved** procedure.

SSEN Distribution Operational Safety Rules 2022

We take pride in our work and workplace.

Page 50 of 158



SAFETY DISTANCE 'X' (FROM LIVE HIGH VOLTAGE CONDUCTORS)

Diagram 1

4.4.2 APPROACH OF PERSONS

(a) Subject to the provisions of Rule 4.4.2 (b), and 4.4.2 (c), no person Shall allow any part of their body to approach exposed High Voltage Conductors, or insulators supporting such Conductors, within the Safety Distances specified in Rule 4.4.1 unless the Conductors have been made safe for work and a Safety Document issued as required by Rule 4.1.1. Please see the SSEN Distribution Approved Tools and Equipment list and catalogue (available via SSEN Distribution intranet pages) for Approved insulated gloves.

In terms of Approved Procedures, please reference:

- SSEN Distribution Operational Safety Manual Section 9.1 – Testing of High Voltage Apparatus;
- SSEN Distribution Operational Safety Manual Section 4.2 – High Voltage Switching and Earthing; and
- SSEN Distribution Operational Safety Manual Section 15 – High Voltage Live Line Work.

If you're not sure, stop and ask for help.

- (b) When a Person is applying an Approved voltage testing device to High Voltage Conductors contained within the open spouts of metal-enclosed switchgear, it is allowable for those parts of the body required to perform the task to approach within the Safety Distances specified in Rule 4.4.1 subject to Approved procedures. Approved insulating gloves Shall be worn.
- (c) When **High Voltage Live Line Work** is being carried out in accordance with **Approved** Hot Glove Procedures, it is allowable for the body to approach within the **Safety Distances** specified in Rule 4.4.1.

4.4.3 OBJECTS BEING HANDLED

- (a) When exposed High Voltage Conductors are not Isolated the only objects which Shall be caused to approach them, or insulators supporting them, within the Safety Distances specified in Rule 4.4.1 Shall be those Approved for High Voltage Live Line Work and Approved voltage testing devices.
- (b) When exposed Conductors are Isolated but not proved Dead, the only objects which Shall be caused to approach them, or insulators supporting them, within the Safety Distances specified in Rule 4.4.1 Shall be insulated devices Approved for High Voltage Live Line Work and Approved voltage testing devices.

4.4.4 WORKING AND ACCESS CLEARANCES

Working and Access Clearances for use by Persons are specified in Appendix A.

Taking account of the nature and location of the work, the hazards and the presence of persons, a **Senior Authorised Person** may determine alternative, fit for purpose, **Working and Access Clearances** whilst ensuring the **Safety Distances** specified in Rule 4.4.1. are maintained both in respect of those persons present and the objects being handled. SSEN Distribution Operational Safety Manual Section 6.2 – Management and Demarcation of Work or Testing in Substations with Exposed Busbar or Gas Insulated Apparatus.

SSEN Distribution Operational Safety Manual Section 7.2 – Management of Work and Access to Towers.

SSEN Distribution Operational Safety Manual Section 6.2 – Management and Demarcation of Work or Testing in Substations with Exposed Busbar or Gas Insulated Apparatus.

4.5 WORK IN SUBSTATIONS AND SWITCHING STATIONS CONTAINING EXPOSED LIVE HIGH VOLTAGE CONDUCTORS

4.5.1 WORK AREA

- (a) When work is to be carried out in a substation or switching station in which there are exposed Live High Voltage Conductors, the work area Shall be properly identified by a Senior Authorised Person. The work area Shall be defined as far as possible by the use of Approved barriers, chains or by other Approved means. These Shall be so arranged that the specified Working and Access Clearances, from the nearest exposed Live Conductor or supporting insulator to ground level or platform or access way which may be required to be used, are established.
- (b) The work area to be defined at ground level **Shall** only be that in which the work is to be carried out.
- (c) If the work cannot be carried out without leaving ground level or a platform or access way, the Working and Access Clearances Shall also be obtained from the nearest exposed Live High Voltage Conductor to the points from which work is actually carried out. In such cases access Shall only be by means of an Approved ladder or other Approved means in accordance with Rules 4.5.4 and 4.5.5. The climbing of structures to gain access is forbidden. In the case of terminal poles, or towers in substations, access Shall be in accordance with an Approved procedure.
- (d) If the work is such that the specified Working and Access Clearances are not sufficient to avoid Danger other suitable arrangements Shall be made.
- (e) The Approved barriers or chains Shall be clearly visible and Shall not be supported by any structure carrying electrical Apparatus or Conductors and Shall not carry any notice. At ground level the section so defined Shall be clearly distinguished in accordance with an Approved procedure. Danger Notices Shall be attached to adjoining Apparatus containing Live Conductors or adjacent Conductor supports at the limits of the work area.

SSEN Distribution Operational Safety Manual Section 6.2 – Management and Demarcation of Work or Testing in Substations with Exposed Busbar or Gas Insulated Apparatus.

Please contact the SSEN Distribution Operational Safety Team, or the Designated Engineer for further guidance on portable ladders of this type and purpose.

If you're not sure, stop and ask for help.

Page 56 of 158

4.5.2 ACCESS TO THE WORK AREA

Where necessary to prevent **Danger** the access and egress ways to and from the work area **Shall** be clearly defined in an **Approved** manner.

4.5.3 WORKING AND ACCESS CLEARANCES

The Working and Access Clearances required at the work area under Rule 4.5.1 Shall be as specified in Rule 4.4.4 (see also Appendix A – Diagram 4).

4.5.4 USE OF PORTABLE LADDERS AND LONG OBJECTS WHERE THERE ARE EXPOSED LIVE CONDUCTORS

NOTE: For the purpose of this Rule, Long Objects are any tool or object which, by virtue of movement or improper use, might infringe the **Safety Distance**.

- (a) Portable ladders **Shall** be of **Approved** type and of no greater length than is required for the work involved.
- (b) Portable ladders and other long objects Shall not be used without the permission of a Senior Authorised Person, who Shall define the conditions of use to the Authorised Person in charge of the work. The movement and erection of such ladders and objects Shall then be carried out only under the Personal Supervision of the Authorised Person in charge of the work, and when moved at ground level they Shall be carried only in a horizontal position and as near to the ground as reasonably practicable.
- (c) Portable ladders provided to allow access to fixed ladders which terminate above ground level, and to provide access in other Approved cases, Shall be padlocked in position or otherwise secured by an Authorised Person while work is being carried out.
- (d) All portable ladders within substations or switching stations Shall be securely locked to a suitable anchorage when not in use.

SSEN Distribution Operational Safety Rules 2022

If it's not safe, we don't do it.

Page 58 of 158

4.5.5 THE MOVEMENT AND USE OF CRANES, SCAFFOLDS, MOBILE ELEVATED WORK PLATFORMS AND OTHER EQUIPMENT

- (a) When cranes, scaffolds, Mobile Elevated Work Platforms and other equipment and materials transported by vehicles or otherwise are taken into or out of a substation the route to be followed Shall be agreed by a Senior Authorised Person. The cranes or other equipment Shall be connected to the substation earthing System as soon as reasonably practicable.
- (b) The limits of operation of such equipment Shall be defined by a Senior Authorised Person to an Authorised Person who Shall be in charge of the work and thereafter the equipment Shall be erected or moved only within these limits under the Personal Supervision of the Authorised Person.

4.5.6 DANGER NOTICES, BARRIERS AND SCREENS

Danger Notices, barriers and screens Shall be fixed or moved only by, or under the Personal Supervision of a Senior Authorised Person.

4.5.7 ADVERSE WEATHER CONDITIONS

In the event or near approach of a lightning storm, work on exposed **Conductors** in outdoor substations or outdoor switching stations, or on **Apparatus** directly connected to exposed **Conductors**, **Shall** cease immediately where necessary to prevent **Danger**.

SSEN Distribution Operational Safety Manual Section 5.2 – Use and Completion of Operational Documents.

4.6 PERMITS-TO-WORK

4.6.1 AUTHORITY FOR ISSUE

- (a) A Permit-to-Work Shall be issued by a Senior Authorised Person before any work is carried out on any Apparatus or Conductor.
- (b) **Permits-to-Work Shall** only be issued with the authority of the **Control Engineer**, who **Shall** maintain an **Approved** record of the issue and cancellation of each **Permit-to-Work**.

4.6.2 PROCEDURE FOR ISSUE AND RECEIPT

- (a) A Permit-to-Work Shall be explained and issued to the Person in direct charge of the work, who after reading its contents and confirming that they understand it, and are conversant with the nature and extent of the work to be done, Shall sign its receipt and its duplicate. The recipient Shall confirm their understanding by explaining the safe working area, the work to be carried out, and precautions required. The recipient Shall also ensure that the Permit-to-Work is effectively explained to the other members of the Working Party in accordance with an Approved procedure.
- (b) The recipient of a Permit-to-Work Shall be a Competent Person who Shall retain the Permit-to-Work in their possession at all times whilst work is being carried out.
- (c) Where more than one Working Party is involved, a Permitto-Work Shall be issued to the Competent Person in direct charge of each Working Party and these Shall, where necessary, be cross-referenced one with another.

4.6.3 PROCEDURE FOR CLEARANCE AND CANCELLATION

- (a) A **Permit-to-Work Shall** be cleared and cancelled:
 - when work on the Apparatus or Conductor for which it was issued has been completed;
 - when it is necessary to issue a Sanction-for-Test in which case all Permits-to-Work that are associated with the Apparatus and Conductors to be tested Shall be cleared and cancelled or cleared and suspended in accordance with Rule 4.6.4;

SSEN Distribution Operational Safety Manual Section 5.2 – Use and Completion of Operational Documents.

SSEN Distribution Operational Safety Manual Section 5.2 – Use and Completion of Operational Documents.

Page 62 of 158

- (iii) when it is necessary to change the **Person** in charge of the work detailed on the **Permit-to-Work**; unless the document is transferred in accordance with Rule 4.6.5; or
- (iv) at the discretion of a **Senior Authorised Person** when it is necessary to interrupt or suspend the work detailed on the **Permit-to-Work**.
- (b) The recipient Shall sign the clearance and return the Permitto-Work to a Senior Authorised Person who Shall cancel it and inform the Control Engineer. In all cases the recipient Shall indicate in the clearance section whether Additional Earths have been "removed" or "accounted for", whether the work is "complete" or "incomplete" and that all gear and tools "have" or "have not" been removed.
- (c) Where more than one Permit-to-Work has been issued for work on High Voltage Apparatus or Conductors associated with the same Circuit Main Earths, the Control Engineer Shall ensure that all such Permits-to-Work have been cancelled before the Circuit Main Earths are removed.

4.6.4 PROCEDURE FOR TEMPORARY WITHDRAWAL OR SUSPENSION

Where there is a requirement for a **Permit-to-Work** to be temporarily withdrawn or suspended this **Shall** be in accordance with an **Approved** procedure.

4.6.5 PROCEDURE FOR TRANSFER

Where there is a requirement for a **Permit-to-Work** to be transferred between appropriately **Competent Persons** this **Shall** be done in accordance with an **Approved** procedure.

4.6.6 MINOR TESTING UNDER A PERMIT-TO-WORK

Where there is a requirement for minor testing under a **Permit-to-Work**, this **Shall** be in accordance with an **Approved** procedure.

SSEN Distribution Operational Safety Manual Section 2 – System Control Procedures.

SSEN Distribution Operational Safety Manual Section 5.2 – Use and Completion of Operational Documents.

4.7 SANCTIONS-FOR-TEST

4.7.1 AUTHORITY FOR ISSUE

- (a) A Sanction-for-Test Shall be issued by the Senior Authorised Person initiating the testing under these OSR before any testing is carried out on any Apparatus or Conductor.
- (b) A Sanction-for-Test Shall only be issued with the authority of the Control Engineer, who Shall maintain an Approved record of the issue and cancellation of each Sanction-for-Test.

4.7.2 PROCEDURE FOR ISSUE AND RECEIPT

- (a) A Sanction-for-Test Shall be explained and issued to the Authorised Person in direct charge of the testing, who after reading its contents and confirming that they understand it, and are conversant with the nature and extent of the testing to be done, Shall sign its receipt and its duplicate. The recipient Shall confirm their understanding by explaining the Apparatus to be tested, the testing to be carried out, and precautions required. The recipient Shall also ensure that the Sanction-for-Test is effectively explained to the other members of the testing party in accordance with an Approved procedure.
- (b) The recipient of a Sanction-for-Test Shall be an Authorised Person who Shall retain the Sanction-for-Test in their possession at all times whilst testing is being carried out.

4.7.3 PROCEDURE FOR CLEARANCES AND CANCELLATIONS

When testing on **Apparatus** for which a **Sanction-for-Test** has been issued is suspended or completed the recipient **Shall** sign the clearance and return the **Sanction-for-Test** to a **Senior Authorised Person** who **Shall** cancel it and inform the **Control Engineer**.

SSEN Distribution Operational Safety Manual Section 5.2 – Use and Completion of Operational Documents.

Where needed, please contact the SSEN Distribution Operational Safety Team, or the Designated Engineer for further guidance on Section 4.8.1.

If you're not sure, stop and ask for help.

4.7.4 PROCEDURE FOR TEMPORARY WITHDRAWAL OR SUSPENSION

Where there is a requirement for a **Sanction-for-Test** to be temporarily withdrawn or suspended this **Shall** be in accordance with an **Approved** procedure.

4.7.5 MINOR WORK UNDER A SANCTION-FOR-TEST

Where there is a requirement for minor work under a **Sanction-for-Test**, this **Shall** be in accordance with an **Approved** procedure.

4.8 LIMITATIONS-OF-ACCESS

4.8.1 AUTHORITY FOR ISSUE

- (a) A Limitation-of-Access Shall be issued by a Senior Authorised Person or an Authorised Person specially authorised to do so when it is considered necessary to have written instructions to avoid Danger and when a Permit-to-Work or a Sanction-for-Test is not applicable.
- (b) In particular, a **Limitation-of-Access** may be issued for the following types of activity when there is **Danger**:
 - work in proximity to, but outside the Working and Access Clearance from, exposed Live High Voltage Conductors;
 - (ii) work on **Plant** operated by or containing compressed air or other gases; or
 - (iii) such other access or work as specified by an **Approved** procedure.

SSEN Distribution Operational Safety Manual Section 5.2 – Use and Completion of Operational Documents.

4.8.2 PROCEDURE FOR ISSUE AND RECEIPT

- (a) A Limitation-of-Access Shall be explained and issued to the Person in direct charge of the work who after reading its contents and confirming that they understand it, and are conversant with the nature and extent of the work to be done, Shall sign its receipt and its duplicate. The recipient Shall confirm their understanding by explaining the work to be carried out, and precautions required. The recipient Shall also ensure that the Limitation-of-Access is effectively explained to the other members of the Working Party in accordance with an Approved procedure.
- (b) The recipient of a Limitation-of-Access Shall be a Competent Person who Shall retain the Limitation-of-Access in their possession at all times whilst work is being carried out.
- (c) Where more than one Working Party is involved, a Limitation-of-Access Shall be issued to the Competent Person in direct charge of each Working Party.

4.8.3 PROCEDURE FOR CLEARANCE AND CANCELLATION

A **Limitation-of-Access Shall** be cleared by the recipient signing the clearance and then returning the **Limitation-of-Access** for cancellation to a **Senior Authorised Person** or **Authorised Person** specially authorised to do so.

Please see the SSEN Distribution Approved Tools and Equipment list and catalogue (available via SSEN Distribution intranet pages) for Approved Voltage testing devices and earthing equipment.

In terms of Approved Procedures, please reference:

- SSEN Distribution Operational Safety Manual Section 9.1 – Testing of High Voltage Apparatus; and
- SSEN Distribution Operational Safety Manual Section 4.2 – High Voltage Switching and Earthing.

5. PROCEDURES FOR WORK ON PARTICULAR ITEMS OF PLANT, APPARATUS OR CONDUCTORS

5.1 GENERAL SAFETY PRECAUTIONS

5.1.1 The safety precautions detailed in Section 4 for work on or near High Voltage Systems Shall apply.

5.1.2 ZONE OF WORK

When, in order to work on particular items of **Plant, Apparatus** or **Conductors**, a section of the **System** larger than the zone of work is **Isolated** and **Earthed** (as, for example, in the case of work on ring main units) the Safety Rules specified in Section 5 relating to isolation and earthing and the requirements for **Personal Supervision** by the **Senior Authorised Person**, for such work may be waived in **Approved** circumstances provided that:

- before the waiver the normal requirements of Rule 4.1.1 are applied in full;
- (b) all High Voltage Apparatus and Conductors within the zone of work are connected to the Circuit Main Earths at the time when the specified Apparatus or Conductors are released for work or testing by the issue of a Safety Document; and
- (c) an **Approved** procedure applies.

In these circumstances, the recipient of the **Safety Document** may, in the course of work or testing, disconnect from the **Circuit Main Earths** as required, any **Apparatus** or **Conductors** within the zone of work.

The Senior Authorised Person Shall, at the time of issue of the Safety Document, demonstrate to the recipient by Approved means that the Apparatus or Conductors are Dead.

The Apparatus and Conductors Shall be reconnected to the Circuit Main Earths before the Safety Document is cleared, unless the Circuit Main Earths, the Apparatus or the Conductors have been permanently removed from the System. SSEN Distribution Operational Safety Manual Section 4.2 – High Voltage Switching and Earthing. Precautions **Shall** be taken to avoid **Danger** from potential differences arising from remote **Earth** points, by bonding and earthing **Conductors** in an **Approved** manner at a point as near as possible to the point of work.

5.2 REMOTELY AND AUTOMATICALLY CONTROLLED EQUIPMENT

Before work is carried out on remotely or automatically controlled equipment such as circuit-breakers, isolators, tap changing gear or air compressors, all remote control and automatic features **Shall** first be rendered inoperative and, where the facility exists, **Safety Locked** off and **Caution Notices** posted. Whilst such work is in progress, no work **Shall** be carried out on the controlling equipment and associated wiring or relays, except by an **Authorised Person** or **Competent Person** acting under their **Personal Supervision**. In this case the **Distribution Control Engineer Shall** be informed but no work of this kind **Shall** be carried out if it could restore the remote control or automatic features.

5.3 WITHDRAWABLE APPARATUS

- 5.3.1 When withdrawable High Voltage Apparatus has been disconnected from all supplies and removed from its normal housing, its Conductors Shall be discharged to Earth, but need not remain connected to Earth. Where a risk assessment shows there is no Danger from stored electrical energy, it is not necessary to discharge the withdrawable Apparatus. Care Shall also be taken to risk assess and safely control any other types of stored energy potentially present in the withdrawable Apparatus.
- **5.3.2** All spout shutters not required to be opened for immediate work or operation **Shall** where practicable be locked shut or otherwise made inaccessible.
- **5.3.3** Work, at the location, on withdrawable **High Voltage Apparatus** that has been disconnected in accordance with Rule 5.3.1 **Shall** be carried out under a **Limitation-of-Access**.

Please see the SSEN Distribution Approved Tools and Equipment list and catalogue (available via SSEN Distribution intranet pages) for Approved items such as resistive Voltage testing devices, and earthing equipment.

5.4 BUSBAR SPOUTS, BUSBARS AND BUSBAR CONNECTIONS OF MULTI-PANEL SWITCHBOARDS

5.4.1 ISOLATION

When work is to be carried out on busbar spouts, busbars and busbar connections, all of the following isolation procedures **Shall** be carried out:

- (a) the section of the busbar on which work is to be carried out Shall be Isolated from all points of supply from which it can be made Live;
- (b) the isolating arrangements Shall be locked so that they cannot be operated and, where practicable, the shutters of Live spouts locked shut. Where duplicate circuit-breakers or switches in one tank or on-load selectors are installed, and it is not possible to isolate them from all points of supply, then all circuit-breakers or switches that can be closed on to the busbars on which work is to be carried out Shall have their mechanisms locked in the open position and the closing mechanism Shall be rendered inoperative;
- (c) **Caution Notices Shall** be attached at all points where the busbars can be made **Live**; and
- (d) Danger Notices Shall be attached on or adjacent to Apparatus containing Live Conductors at the limits of the zone of work.

5.4.2 EARTHING

- (a) Where practicable the section of busbar on which work is to be carried out Shall be checked by means of an Approved voltage testing device to verify that it is not Live. The checking with the voltage testing device Shall be carried out on the panel at which the Circuit Main Earth is to be applied.
- (b) **Circuit Main Earths** of an **Approved** type **Shall** be applied at a panel, other than that at which work is to be undertaken, on the **Isolated** section of busbars. The insertion of the hand or any tool into contact spouts for this purpose is forbidden.
- 5.4.3 A Permit-to-Work or Sanction-for-Test Shall be issued in accordance with Rules 4.6 or 4.7.

Please see the SSEN Distribution Approved Tools and Equipment list and catalogue (available via SSEN Distribution intranet pages) for Approved Voltage testing devices and earthing equipment.

In terms of Approved Procedures, please reference:

- SSEN Distribution Operational Safety Manual Section 9.1 – Testing of High Voltage Apparatus;
- SSEN Distribution Operational Safety Manual Section 4.2 – High Voltage Switching and Earthing; and
- SSEN Distribution Operational Safety Manual Section 6.3 – Work on High Voltage Plant and Apparatus.

5.4.4 WORK

Before obtaining the receipt signature on the **Permit-to-Work** the **Senior Authorised Person** who is issuing the **Permit-to-Work Shall**, at the point of work, satisfy themselves that the recipient is aware of the location of all adjacent **Live High Voltage Apparatus** and of the safety precautions to be taken by the recipient. Immediately after the **Senior Authorised Person** has obtained the receipt signature on the **Permit-to-Work** and before any work is carried out, then:

- (i) where work is to be carried out on busbar spouts it Shall be carried out under the Personal Supervision of the Senior Authorised Person who Shall identify the busbar spouts to be worked on and where necessary provide access by removing any locks applied to such spout shutters. They Shall then prove that each spout is Dead by means of an Approved voltage testing device or other Approved means before any work is undertaken on the spout; and
- (ii) where work is to be carried out on busbars or busbar connections the Senior Authorised Person Shall identify in an Approved manner where access is to be made. Access Shall then be made, by the removal of the appropriate cover plates, under the Personal Supervision of the Senior Authorised Person who, until they are satisfied that no further access is required to complete the work and that they have taken such action to prove, where practicable, that each busbar or busbar connection in the working area is Dead by means of testing with an Approved voltage testing device or other Approved means. No further access Shall be made to other parts of the switchboard during the course of the work.

Please see the SSEN Distribution Approved Tools and Equipment list and catalogue (available via SSEN Distribution intranet pages) for Approved items such as resistive Voltage testing devices, and earthing equipment.

SSEN Distribution Operational Safety Manual Section 4.9 – Portable Earthing for Metal-Enclosed Switchgear.

5.5 FEEDER SPOUTS AND CONNECTIONS, VOLTAGE TRANSFORMER SPOUTS AND CONNECTIONS AND SINGLE PANEL BUSBAR SPOUTS AND CONNECTIONS

5.5.1 ISOLATION

When work is to be carried out on feeder and voltage transformer spouts or connections, or on the busbar spouts or connections of a single panel, the following procedures **Shall** be carried out:

- the spouts or connections on which work is to be carried out Shall be lsolated from all points of supply from which they can be made Live;
- (b) the isolating arrangements Shall be locked so that they cannot be operated and the shutters of Live spouts Shall be locked shut;
- (c) **Caution Notices Shall** be attached at all points where the circuit can be made **Live**; and
- (d) Danger Notices Shall be attached, where applicable, on or adjacent to the Apparatus containing Live Conductors at the limits of the zone of work.

5.5.2 EARTHING

- (a) Where practicable the spout contacts or connections Shall be checked by means of an Approved voltage testing device to verify that they are not Live.
- (b) The circuit Shall be Earthed with Approved earthing equipment at the point of work and, where reasonably practicable, at all points of isolation from the supply. Any special appliances used for the purposes of earthing metalenclosed switchgear Shall also be Approved but the insertion of the hand or any tool into contact spouts for this purpose is forbidden.
- (c) Where the spouts are connected to an overhead line circuit, a Circuit Main Earth Shall be applied at a point nearest to the point of work where access to the Conductors can safely be obtained.

Please see the SSEN Distribution Approved Tools and Equipment list and catalogue (available via SSEN Distribution intranet pages) for Approved Voltage testing devices and earthing equipment.

In terms of Approved Procedures, please reference:

- SSEN Distribution Operational Safety Manual Section 9.1 – Testing of High Voltage Apparatus; and
- SSEN Distribution Operational Safety Manual Section 4.2 – High Voltage Switching and Earthing.

5.5.3 A Permit-to-Work or Sanction-for-Test Shall be issued in accordance with Rules 4.6 or 4.7. Where the work to be done requires removal of the Circuit Main Earths at the point of work the Permit-to-Work Shall state how this is permitted under Rule 5.5.4(i).

5.5.4 WORK

Before obtaining the receipt signature on the **Permit-to-Work**, the **Senior Authorised Person** who is issuing the **Permit-to-Work Shall**, at the point of work, satisfy themselves that the recipient is aware of the location of adjacent **Live High Voltage Apparatus** and of the safety precautions to be taken by the recipient. Immediately after the **Senior Authorised Person** has obtained the receipt signature on the **Permit-to-Work**, and before any work is carried out, then:

- where the work is to be carried out on the feeder, voltage (i) transformer or busbar spouts on a single panel unit, it Shall be carried out under the Personal Supervision of a Senior Authorised Person who, notwithstanding the requirements of Rule 4.3.4.(a) may, where necessary, remove the **Circuit** Main Earths at the point of work and provide access by removing any locks applied to such spout shutters. They Shall then prove that each spout is **Dead** by means of an **Approved** voltage testing device or other **Approved** means before any work is undertaken on the spout. On completion of the work, the Circuit Main Earths Shall be re-applied, if necessary, before the **Permit-to-Work** is cancelled. If the only earthing devices that can be applied to the circuit are those applied to the spouts and are Circuit Main Earths then, while the work is in progress no other work Shall be carried out to the circuit connected to those spouts; and
- (ii) where work is to be carried out on feeder or voltage transformer connections or single panel busbars or connections the Senior Authorised Person Shall identify in an Approved manner where access is to be made. Access Shall then be made by the removal of the appropriate cover plates under the Personal Supervision of the Senior Authorised Person who Shall continue to provide Personal Supervision until they are satisfied that no further access is required to complete the work and that they have taken such action to prove, where practicable, that each connection or busbar in the working area is Dead by means of testing with an Approved voltage testing device or other Approved means. No further access Shall be made to other parts of the switchboard during the course of the work.

Please refer to the SSEN Distribution Operational Safety Manual, or contact the SSEN Distribution Operational Safety Team, or the Designated Engineer, for further guidance on compressed air systems.

If you're not sure, stop and ask for help.

SSEN Distribution Operational Safety Manual Section 4.2 – High Voltage Switching and Earthing.

SSEN Distribution Operational Safety Manual Section 6.3 – Work on High Voltage Plant and Apparatus.

Please refer to the SSEN Distribution Operational Safety Manual (section 6.2), or contact the SSEN Distribution Operational Safety Team, or the Designated Engineer, for further guidance on equipment containing SF6 gas.

If you're not sure, stop and ask for help.

5.6 HIGH VOLTAGE APPARATUS AND PLANT OPERATED BY OR CONTAINING COMPRESSED AIR OR OTHER GASES OR OPERATED BY HYDRAULIC POWER

5.6.1 COMPRESSED AIR

All the following precautions **Shall** be taken before any work other than operating adjustments is carried out:

- (a) if the work area includes the compressor plant, then the supply to the prime mover of the compressor Shall be switched off and any such switch and/or control handle operating the switch Safety Locked in the off or neutral position as appropriate, and a Caution Notice Shall be attached at each such position;
- (b) all valves positioned between the part of the System to remain in service and the work area Shall be closed and locked in the closed position by Safety Locks, and a Caution Notice Shall be attached at each position. In addition, the supply to any such valve that is power operated Shall be rendered inoperative and where the facility exists the power supply Safety Locked in the off position;
- (c) the compressed air in any work area Shall be released before work commences, and Approved methods Shall be used to ensure that the equipment or pipes concerned Shall remain open to atmosphere for the duration of the work; and
- (d) all keys for Safety Locks fitted under the provisions of this Rule Shall be placed in a Key Safe, in the possession of a Senior Authorised Person or in accordance with an Approved procedure.

5.6.2 OPERATING ADJUSTMENTS

Notwithstanding the requirement of Rule 5.6.1, operating adjustments on equipment operated by or containing compressed air, which require the normal air supply, **Shall** be carried out under the **Personal Supervision** of an **Authorised Person**.

5.6.3 EQUIPMENT CONTAINING SF6 OR OTHER DIELECTRIC GAS

Access to or work on equipment containing SF_6 or other dielectric gas **Shall** be carried out in accordance with an **Approved** procedure.

SSEN Distribution Operational Safety Manual Section 6.3 – Work on High Voltage Plant and Apparatus.

Please refer to the SSEN Distribution Operational Safety Manual, or contact the SSEN Distribution Operational Safety Team, or the Designated Engineer, for further guidance on transformers supplying traction loads.

If you're not sure, stop and ask for help.

SSEN Distribution Operational Safety Manual Section 6.3 – Work on High Voltage Plant and Apparatus. 5.6.4 Where the additional safety precautions required for work on associated Apparatus are not detailed on a **Permit-to-Work**, then in addition a **Limitation-of-Access Shall**, where necessary, be used in accordance with Rule 4.8.

5.7 TRANSFORMERS

5.7.1 ISOLATION

- (a) When work within the terms of Rule 4.1 is to be carried out on the connections to or the windings of a transformer, the switchgear or fuse gear controlling all windings Shall be opened or the windings or connections Isolated by other Approved means from Live Conductors.
- (b) Additionally, to prevent the possibility of the transformer being made Live by back-feed all Low Voltage fuses or links on associated voltage and auxiliary transformers Shall be withdrawn or the voltage and auxiliary transformers Isolated. The fuse and link carriers Shall be locked where reasonably practicable.
- (c) The transformer Shall be Isolated from all common neutral earthing equipment from which it might become Live. Except for the isolation of transformers supplying traction loads, which Shall be in accordance with an Approved procedure, this does not require the disconnection of solidly Earthed neutrals or neutral equipment connected solely to the transformer on which work is to be done.
- (d) Where work is to be carried out on a High Voltage to Low Voltage transformer and the Low Voltage windings of the transformer are controlled by a switch or isolator, the switch or isolator Shall, be secured open in an Approved manner.
- (e) In other cases, arrangements Shall be made to ensure that the Low Voltage windings are Isolated from all sources of Low Voltage supply.
- (f) Before any withdrawable voltage transformer is **Isolated** or reconnected the associated **High Voltage** connections **Shall**, where reasonably practicable, be made **Dead**. If it is suspected that a voltage transformer is faulty the associated busbars or feeder connections **Shall** be made **Dead** before it is **Isolated**.

SSEN Distribution Operational Safety Manual Section 4.2 – High Voltage Switching and Earthing

Please see the SSEN Distribution Approved Tools and Equipment list and catalogue (available via SSEN Distribution intranet pages) for Approved Capacitor earthing equipment.

Further guidance can be obtained from the SSEN Distribution Operational Safety Team, or the Designated Engineer.

If you're not sure, stop and ask for help.

- (g) **Caution Notices Shall** be attached at all points of isolation including at **Low Voltage**.
- (h) All keys for Safety Locks fitted under the provisions of this Rule Shall be placed in a Key Safe, in the possession of a Senior Authorised Person or in accordance with an Approved procedure.

5.7.2 EARTHING

The transformer **Shall** be **Earthed** in accordance with Rules 4.1.1 (c).

- 5.7.3 Before a **Permit-to-Work** or **Sanction-for-Test** is issued the **Senior Authorised Person Shall**, so far as reasonably practicable, at the point of work, identify the transformer to be worked on, in accordance with Rules 4.1.1 (e).
- 5.7.4 A **Permit-to-Work** or **Sanction-for-Test Shall** be issued in accordance with Rules 4.6 or 4.7.

5.8 HIGH VOLTAGE STATIC CAPACITORS

5.8.1 ISOLATION

Static capacitors **Shall**, in accordance with Rule 4.1.1, be **Isolated** from all **Live Conductors**, locked off where practicable and **Caution Notices** fixed.

5.8.2 EARTHING

After the **Circuit Main Earths** have been applied to the instructions of the **Control Engineer**, the following earthing operations **Shall** be carried out under the **Personal Supervision** of a **Senior Authorised Person** in the following sequence:

- (i) apply **Approved** capacitor earthing devices to the capacitor frames; and
- (ii) apply **Approved** capacitor earthing devices to the common connections of each group of capacitors see 5.8.4(b).
- **5.8.3** A **Permit-to-Work** or **Sanction-for-Test Shall** then be issued in accordance with Rules 4.6 or 4.7.

SSEN Distribution Operational Safety Manual Section 8 – Access and Work on High Voltage Underground Cables.

SSEN Distribution Operational Safety Manual Section 8 – Access and Work on High Voltage Underground Cables.

SSEN Distribution Operational Safety Manual Section 8 – Access and Work on High Voltage Underground Cables.

SSEN Distribution Operational Safety Manual Section 8.2 – Access and Work on High Voltage Underground Cable Ancillary Systems.

5.8.4 WORK

- (a) Approved Additional Earths Shall then be applied to the capacitor units at the point of work. These Additional Earths Shall be applied or removed only under the Personal Supervision of a Senior Authorised Person.
- (b) Capacitor units **Shall** be short-circuited and remain shortcircuited when removed from the circuit or in cases where earthing in accordance with Rule 5.8.2(ii) is impracticable.

5.9 HIGH VOLTAGE CABLES

- 5.9.1 All cables Shall be treated as Live (especially cables which are either damaged, or have exposed Conductors), until proved Dead by an Approved procedure. No person Shall touch the insulation which covers any Conductor subject to High Voltage unless the Conductor has been made safe in accordance with Rule 4.1.1.
- 5.9.2 Before issuing a Permit-to-Work for work on a High Voltage cable, the Senior Authorised Person, in addition to the procedure of Rule 4.1.1 Shall, at the point of work, in accordance with an Approved procedure identify the cable to be worked on, then by use of an Approved spiking procedure or other Approved means, prove it Dead. The Distribution Control Engineer Shall be informed before and immediately after any cable is spiked.
- 5.9.3 Where work is to be carried out on the insulated sheath system of a High Voltage cable route, additional precautions to prevent Danger from any sheath voltages Shall be taken in accordance with Approved procedures.
- 5.9.4 Where work is to be carried out on any cable or ancillary equipment associated with a High Voltage cable route which might be subjected to induced voltages from other Live circuits in their proximity, then such work Shall only be carried out in accordance with Approved procedures (see also Rule 8.3.2). When required by the Approved procedure, a Permit-to-Work or Sanction-for-Test Shall be issued in accordance with Rules 4.6 or 4.7.

Reminder – it is good practice for a Competent Person receiving a Safety Document to check, double-check and if necessary, challenge the safety precautions confirmed by the Senior **Authorised Person** issuing the Safety Document.

5.10 HIGH VOLTAGE OVERHEAD LINES - GENERAL

Before issuing a **Permit-to-Work** for work on a **High Voltage** overhead line, in accordance with Rule 4.1.1, the **Conductors Shall** be bonded together and connected to **Earth**. Where **Earthed** metalwork is present, it **Shall** be bonded to the **Earthed Conductors**.

No **Person Shall** access any pole, tower or structure subject to a **Safety Document** unless:

- they have confirmed that the poles, towers or supports are those detailed on the Safety Document;
- they have also identified the pole, tower or support by any additional means where provided e.g. circuit designation colours;
- (iii) the circuit as defined within the Safety Document at the intended point of work can be seen from ground to be connected to Earth with Approved earthing equipment. If not, then before work commences an Additional Earth Shall be applied in accordance with 5.10.3; and
- (iv) they are instructed to do so by the recipient of the Safety Document. All instructions given by the recipient Shall be in the presence of the Person who is accompanying the climber who Shall remain in visual contact for the duration of the work.

LINES IN PROXIMITY

If there are other overhead lines in proximity to the one to be worked on, the issuer and recipient of the **Safety Document Shall** ensure that the climber and the **Person** accompanying the climber are warned of the additional **Danger**.

5.10.1 SAFE ACCESS

Access arrangements **Shall** be in accordance with Rule 3.3.

- (a) Where ladders are used they **Shall** be of an **Approved** type.
- (b) Caution Notices, Danger Notices, barriers and screens Shall be fixed or moved only under the Personal Supervision of an Authorised Person.

SSEN Distribution Operational Safety Manual Section 7 – Access and Work on High Voltage Overhead Lines.

SSEN Distribution Operational Safety Manual Section 7 – Access and Work on High Voltage Overhead Lines.

Page 92 of 158

(c) No Person Shall, at a point more than 3.7 metres from ground level, touch any unearthed pole or structure supporting Live High Voltage Apparatus unless adequate precautions have been taken to prevent Danger from leakage currents in accordance with an Approved procedure.

5.10.2 USE OF CIRCUIT COLOURS, NUMBERS OR SYMBOLS

When circuit colours, numbers or symbols are used as part of the identity of a circuit the following rules **Shall** apply:

- (a) The Senior Authorised Person Shall inform and agree the circuit colours, numbers or symbols with the Control Engineer;
- (b) The Senior Authorised Person Shall write the circuit colours, numbers or symbols in the Safety Document. The recipient of the Safety Document Shall check that they are the correct colours, numbers or symbols and initial the statement of circuit colours, numbers or symbols in the presence of the Senior Authorised Person issuing the Safety Document. The Senior Authorised Person Shall provide the recipient of the Safety Document with sufficient numbers of wristlets; and
- (c) Each Person who will work on Apparatus for which a Safety Document bearing circuit colours or symbols has been issued Shall be provided with a wristlet or identification tag marked with the circuit colours or symbols and Shall wear it in such a manner that it will be readily visible to the user during the whole period they are engaged on the work. On conclusion of the work the wristlets or Identification tags Shall be returned by the recipient of the Safety Document to the Senior Authorised Person.

5.10.3 ADDITIONAL EARTHS

(a) When required, and before work commences on a High Voltage overhead line, Additional Earths Shall be applied at or as near as practicable to the points of work in accordance with an Approved procedure. All Conductors Shall be bonded together and connected to Earth. Where Earthed metalwork is present it Shall be bonded to the Earthed Conductors. SSEN Distribution Operational Safety Manual Section 7 – Access and Work on High Voltage Overhead Lines.

Please see the SSEN Distribution Approved Tools and Equipment list and catalogue (available via SSEN Distribution intranet pages) for Approved earthing equipment.

Further guidance can be obtained from the SSEN Distribution Operational Safety Team, or the Designated Engineer.

If you're not sure, stop and ask for help.

- (b) The number and position of Additional Earths applied after a Permit-to-Work is issued Shall normally be the responsibility of the recipient of the Permit-to-Work. Where special precautions have to be taken the point of application of Additional Earths Shall be specified by the Senior Authorised Person in accordance with an Approved procedure.
- (c) Where line Conductors are to be disconnected, Approved earthing devices Shall be applied on each side of the intended break before the Conductors are disconnected. Where Conductors are to be reconnected across an existing break, Approved earthing devices Shall be applied on each side of the break before the Conductors are reconnected.
- (d) Additional Earths may only be applied by the recipient of a Permit-to-Work or Sanction-for-Test or by a Competent Person under their Personal Supervision.
- (e) The Additional Earths Shall remain in position during the progress of the work and may only be removed by a Competent Person after all other members of the Working Party have descended the pole or tower on completion of the work.
- (f) When painting towers the **Additional Earths** and pennants may be removed by a **Competent Person** in sequence as work proceeds down the tower.
- (g) Additional Earths used by a Working Party Shall be issued by and Shall be returned to the recipient of the Permit-to-Work who Shall ascertain that all the Additional Earths issued have been returned, or accounted for, before the Permit-to-Work is cleared. When the recipient of a Permitto-Work clears and returns the Permit-to-Work to a Senior Authorised Person, the recipient clearing the Permit-to-Work Shall ensure that the Senior Authorised Person is aware of the position of any Additional Earths that have not been removed.

SSEN Distribution Operational Safety Rules 2022

If you're not sure, stop and ask for help.

Page 96 of 158

5.10.4 SUSPENSION OF WORK

If a **Working Party** leaves a line at any time then, before work is restarted, the **Competent Person** in receipt of the **Permit-to-Work Shall** re-identify the line in accordance with Rule 5.11.1, **Shall** verify that all **Earths** adjacent to the point of work are still in position and **Shall** re-instruct the **Working Party** on the work covered by the **Permit-to-Work**.

5.10.5 WORK ON OVERHEAD LINES CARRYING LIVE HIGH VOLTAGE CONDUCTORS

5.10.5.1 HIGH VOLTAGE LIVE LINE WORK ON OVERHEAD LINES

High Voltage Live Line Work, connections to or disconnections from a **High Voltage** overhead line or **Live** line testing may be carried out with the **Conductors Live**, but only in accordance with Section 6 of these **OSR**.

5.10.5.2 ACCESS TO POLES OR TOWERS BY A COMPETENT PERSON

General access below any **Conductor** may be permitted to a **Competent Person** on any pole or tower supporting **Live High Voltage Conductors** provided that the requirements of Rules 4.4 and 5.10.1 are observed. Where appropriate, a marker or markers **Shall** be placed on the pole or tower as an indication of the safe **Working and Access Clearance** (see also **Appendix A** – Diagrams 2 and 3).

5.10.6 WORK ON UPPER PORTIONS OF TOWERS CARRYING LIVE CONDUCTORS

- (a) When work is to be carried out on towers with all Conductors Live, above the position specified in Rule 5.10.5.2, the zone of work and/ or route for climbing Shall be established by a Senior Authorised Person and a Limitation-of-Access Shall be issued and the Control Engineer notified.
- (b) Where reasonably practicable work Shall be carried out from within the body of the tower, where the design of the tower permits. Work and climbing on the outside faces of a tower Shall be in accordance with an Approved procedure. No part of a Person's body or tool that is being carried or used Shall

SSEN Distribution Operational Safety Manual Section 7.2 – Management of Work and Access to Towers.

SSEN Distribution Operational Safety Manual Section 7 – Access and Work on High Voltage Overhead Lines.

SSEN Distribution Operational Safety Manual Section 7 – Access and Work on High Voltage Overhead Lines. at any time encroach the **Safety Distance** surrounding a **Live Conductor**.

(c) **Danger Notices**, barriers and screens **Shall** be fixed or moved only in accordance with an **Approved** Procedure.

5.10.7 RUNNING OUT OR LOWERING OF OVERHEAD CONDUCTORS

When any overhead line **Conductor** is to be raised or lowered or otherwise held on temporary supports/ connections, **Approved** procedures **Shall** be followed to ensure that no **Danger** is caused at locations such as road/railway crossings, etc. where other persons might be present.

Where the overhead line **Conductors** pass over or under, or are in close proximity to a **High Voltage** overhead line, a **Senior Authorised Person Shall** determine whether the overhead line is to be made **Dead** or whether other **Approved** procedures are to be applied to adequately avoid **Danger**. When the **High Voltage** overhead line is to be made **Dead** the requirements of Rule 4.1.1 **Shall** apply and a **Permit-to-Work Shall** be issued.

When other **Approved** procedures are to be applied the work **Shall** either be supervised by a **Senior Authorised Person** or a **Limitation-of-Access Shall** be issued. In all instances the **Control Engineer** responsible for the existing overhead line **Shall** be informed of the work and where appropriate, auto-reclosing facilities on the circuit concerned **Shall** be temporarily suspended.

5.10.8 WORK ON AUXILIARY CABLES SUSPENDED ON A CATENARY BELOW HIGH VOLTAGE OVERHEAD LINES

Where work is to be carried out on auxiliary cables suspended on a catenary below a **Live High Voltage** overhead line, the same clearances as specified in Rule 4.4.4 **Shall** be observed and the work **Shall** not be carried out at a distance of more than 3m from a supporting pole or tower, unless the **High Voltage** overhead line is made safe in accordance with Rule 4.1.1.

Reminder – when operating and/or working on the System, all Persons should have their Authorisation Certificate and Operational Safety Rule book with them.

5.10.9 ADVERSE WEATHER CONDITIONS

- (a) On the near approach of a lightning storm all work on overhead lines Shall cease immediately where necessary to prevent Danger and the Control Engineer Shall be informed.
- (b) No person Shall patrol an overhead line alone across country during the hours of darkness, or when visibility is dangerously impaired by fog or snow, or when snow drifts, or similar hazards exist.
- (c) If overhead lines are to be patrolled during the hours of darkness, suitable lighting equipment **Shall** be used.

5.11 SINGLE OR MULTIPLE CIRCUIT HIGH VOLTAGE OVERHEAD LINES WITHOUT KEYED FLAG BRACKETS AND WITH ALL CONDUCTORS DEAD

5.11.1 PREPARATION FOR A PERMIT-TO-WORK

The **Senior Authorised Person**, in addition to the procedures of Rules 4.1.1 and 5.10 **Shall** ensure that the line to be worked upon is identified in an **Approved** manner at the point of work and, where practicable, they **Shall** ensure that the line is checked by means of an **Approved** voltage testing device or other **Approved** means to verify that the line is not **Live**. If from the point of work the **Conductor** can be seen to be **Earthed**, the use of a voltage testing device may be dispensed with.

5.11.2 A Permit-to-Work Shall be issued.

5.12 DOUBLE CIRCUIT HIGH VOLTAGE OVERHEAD LINES WITHOUT KEYED FLAG BRACKETS AND WITH ONE CIRCUIT LIVE

5.12.1 PREPARATION FOR A PERMIT-TO-WORK

- (a) Where work is to be carried out on double circuit overhead lines with one circuit Live the following precautions in addition to the provision of Rule 5.11 Shall be taken.
- (b) The **Senior Authorised Person** in charge **Shall** ensure that at the point of work the circuit to be worked upon is identified in an **Approved** manner.

SSEN Distribution Operational Safety Manual Section 7 – Access and Work on High Voltage Overhead Lines.

Please see the SSEN Distribution Approved Tools and Equipment list and catalogue (available via SSEN Distribution intranet pages) for Approved Voltage testing devices.

Further guidance can be obtained from the SSEN Distribution Operational Safety Team, or the Designated Engineer.

If you're not sure, stop and ask for help.

- (c) Where work is to be done on terminal, tee-off or large angle poles or towers of a double circuit line with one circuit Live, Danger might occur due to reduced clearances. The work Shall be done under the Personal Supervision of a Senior Authorised Person at ground level unless special precautions are taken in accordance with an Approved procedure.
- 5.12.2 A Permit-to-Work Shall be issued.

5.12.3 WORK

- (a) Before commencing work and during the course of the work, the requirements of Rule 5.10.3 Shall be complied with to avoid Danger from steelwork being Live or becoming Live.
- (b) A green flag Shall be affixed near ground level on the Dead circuit side of the pole or tower under the Immediate Supervision of the Senior Authorised Person. Similarly, a Danger Notice Shall be affixed on the Live circuit side. Before any Person is allowed access, a Competent Person or Competent Persons at the point of work Shall climb the pole or tower on the Dead side, check that the overhead line is not Live using an Approved voltage testing device or other Approved means, and Shall connect to Earth all three Conductors on that side. Red pennants or Danger Notices Shall be affixed by a Competent Person to the crossarms drawing attention to the Danger of the Live circuit and, in the case of lattice steel towers, Shall be affixed at the junction of the tower with the crossarms carrying the Live circuit.
- (c) The Conductors Shall remain Earthed and the green flags, Danger Notices and the red pennants Shall remain in position throughout the progress of the work. All Earths, Danger Notices and pennants Shall be removed by a Competent Person or Competent Persons only after all other members of the Working Party have descended the pole or tower on completion of the work.

SSEN Distribution Operational Safety Manual Section 7 – Access and Work on High Voltage Overhead Lines.

5.13 SINGLE CIRCUIT HIGH VOLTAGE OVERHEAD LINES WITH KEYED FLAG BRACKETS

- 5.13.1 In addition to the requirements of Rules 4.1.1 and 5.10 the following Rules Shall also apply.
- 5.13.2 The recipient of the **Permit-to-Work** who is also in charge of the **Working Party Shall** personally identify at the point(s) of work the circuit to be worked upon by reference to the route identification, the circuit colours and pole or tower number(s).
- 5.13.3 The recipient of the Permit-to-Work Shall be provided with green flag(s) that fit the keyed flag bracket(s) for the circuit on the pole or tower on which work is to be done, and Shall place the green flag in position on the tower before allowing any Person to climb the pole or tower. The recipient of the Permit-to-Work or the Competent Person who is to apply the Additional Earths Shall then climb the tower and apply Additional Earths in accordance with Rule 5.10.3.

5.14 DOUBLE CIRCUIT HIGH VOLTAGE OVERHEAD LINES WITH KEYED FLAG BRACKETS AND WITH ONE CIRCUIT LIVE

- 5.14.1 In addition to the requirements of Rules 5.10 and 5.13, the following Rules Shall also apply.
- 5.14.2 The recipient of the Permit-to-Work or the Competent Person who is to apply the Additional Earths Shall climb the pole or tower on the side indicated by the green flag, applying Additional Earths in accordance with Rule 5.10.3 and then affix red pennants to the crossarms supporting the circuit not being worked on. The red pennants Shall be positioned at the junction of the crossarms and the pole or tower body. The Person doing this Shall be under Personal Supervision of the document recipient or another Competent Person who is a member of the Working Party from ground level. Pennants Shall be removed by a Competent Person only after all other members of the Working Party have descended the pole or tower on completion of work.
- 5.14.3 When work is to be done on terminal, tee-off or large angle poles or towers of a double circuit line with one circuit Live, Danger might occur due to reduced clearances. The work Shall be done under the Personal Supervision of a Senior Authorised Person at ground level unless special precautions are taken in accordance with an Approved procedure.

SSEN Distribution Operational Safety Rules 2022

We plan, scan, and adapt.

Page 106 of 158

5.15 HIGH VOLTAGE OVERHEAD LINES WITH MORE THAN TWO CIRCUITS WITH ONE OR MORE CIRCUITS LIVE

5.15.1 When work is to be done on multiple circuit **High Voltage** overhead lines with one or more circuits **Live** Rules 4.1.1, 5.15.2, 5.15.3 and 5.15.4, in addition to either Rules 5.10 and 5.12 or 5.13 and 5.14 **Shall** apply.

5.15.2 PREPARATION OF A PERMIT-TO-WORK

The **Senior Authorised Person** in charge of the work **Shall**, at the point of work, identify the circuit to be worked on.

5.15.3 A Permit-To-Work Shall be issued after the zone of work has been checked and the precautions to be observed have been verified with the Person in receipt of the Permit-to-Work.

5.15.4 WORK

Work on one circuit of multiple circuit lines, with one or more other circuits still **Live, Shall** not be carried out except under the following conditions:

- (a) separate means of access Shall be provided to the circuit to be worked on;
- (b) the **Conductors** of each circuit **Shall** be either adequately screened to prevent **Danger** or the **Working and Access**

Clearances from the nearest point of work to the remaining **Live** circuits **Shall** be those specified in Rule 4.4.4; and

(c) Rule 5.12 Shall apply where appropriate. The fixing of green flags or red pennants and Additional Earth connections Shall be carried out under the Personal Supervision of a Senior Authorised Person from ground level. SSEN Distribution Operational Safety Manual Section 15 – High Voltage Live Line Work.

Please see the SSEN Distribution Approved Tools and Equipment list and catalogue (available via SSEN Distribution intranet pages) for Approved Live Line tools and equipment.

Further guidance can be obtained from the SSEN Distribution Operational Safety Team, or the Designated Engineer.

If you're not sure, stop and ask for help.

SSEN Distribution Operational Safety Manual Section 15 – High Voltage Live Line Work.

6. SAFETY PRECAUTIONS FOR HIGH VOLTAGE LIVE LINE WORK ON HIGH VOLTAGE OVERHEAD LINES

6.1 AUTHORISATION

- 6.1.1 No High Voltage Live Line Work Shall be carried out except in accordance with Approved procedures.
- 6.1.2 All staff engaged on High Voltage Live Line Work Shall have received appropriate training and Shall possess written authorisation from SSEN-D to undertake High Voltage Line Work.
- 6.1.3 High Voltage Live Line Work Shall only be undertaken under the Personal Supervision of an Authorised Person who Shall have received training in the procedures and is authorised in writing by SSEN-D to act in this capacity. They Shall be present throughout the whole of the High Voltage Live Line Work.
- 6.1.4 Only Approved tools and equipment Shall be used for High Voltage Live Line Work.

6.2 LIVE LINE TOOLS AND EQUIPMENT

- 6.2.1 Live line tools and equipment Shall be kept in a clean and dry condition and before use Shall be inspected by the Authorised Person referred to in Rule 6.1.3 to ensure that they are clean and dry and in sound condition. If any live line tool or piece of equipment is suspected to be defective it Shall not be used.
- 6.2.2 With the exception of Approved Hot Glove Procedures; where Approved procedures for High Voltage Live Line Work are based specifically on the use of insulating rods, a clear mark Shall be maintained on every live line tool and piece of equipment, where appropriate, indicating the limit of the safe handling position which Shall be not less than the distances specified in Table 2 below.

As applicable, please see the SSEN Distribution Operational Safety Manual Section 15 – High Voltage Live Line Work.

SSEN Distribution Operational Safety Manual Section 15 – High Voltage Live Line Work.

Page 110 of 158

Table 2 - LIVE LINE TOOLS SAFE HANDLING LIMITS

Nominal System Voltage	Minimum Effective Length
Not exceeding 11kV	0.9m
Exceeding 11kV but not exceeding 33kV	1.1m
Exceeding 33kV but not exceeding 66kV	1.3m
Exceeding 66kV but not exceeding 132kV	1.7m

NOTE: - Safe handling limits above 132kV are to be determined by individual company **Approved** procedures.

6.3 GENERAL SAFETY PRECAUTIONS

- 6.3.1 Subject to the conditions allowed by this Section 6 for High Voltage Live Line Work, the safety precautions detailed in Section 4 for work on or near High Voltage Systems Shall apply.
- 6.3.2 High Voltage Live Line Work Shall not take place on any section of High Voltage overhead line where the failure of any component, Conductor or tool could energise an associated or adjacent overhead line which is Dead and Earthed and subject to a Permitto-Work or Sanction-for-Test.
- 6.3.3 Work Shall not commence until the Authorised Person in charge of the High Voltage Live Line Work has advised the Control Engineer of the nature and location of the work to be carried out.

If the circuit on which work is being carried out becomes **Dead** owing to the operation of protective equipment or for any other reason, the **Control Engineer Shall** not sanction the circuit to be re-energised without reference to the **Authorised Person** in charge of the **High Voltage Live Line Work**. Auto-reclose and protection equipment controlling the line **Shall** be managed in accordance with an **Approved** procedure.

6.3.4 No High Voltage Live Line Work Shall commence in unfavourable weather. If in the course of work unfavourable weather develops, work Shall be suspended.

SSEN Distribution Operational Safety Manual Section 15 – High Voltage Live Line Work.

Please see the SSEN Occupational Safety Manual and arrangements for working at height on overhead lines; and

SSEN Distribution Operational Safety Manual Section 7 – Access and Work on High Voltage Overhead Lines.

If you're not sure, stop and ask for help.

SSEN Distribution Operational Safety Manual Section 15 – High Voltage Live Line Work; and Section 7.1 – Management of Work and Access to Poles.

- 6.3.5 If it is necessary to suspend **High Voltage Live Line Work** for any reason, the line and equipment **Shall** be left in a safe condition and the **Control Engineer** informed.
- 6.3.6 Before work commences, all Conductors and associated pole top, line and tower fittings, steelwork and insulators Shall be thoroughly examined at the point of work for signs of incipient failure, through binoculars if necessary, so as to minimise the possibility of failure of these parts during High Voltage Live Line Work. The examination Shall extend to include the adjacent spans and pole or tower on both sides of the point of work.
- 6.3.7 Before displacing Live Conductors adequate precautions Shall be taken to avoid Danger and to ensure safety including that of members of the public. Safe Working and Access Clearances, in accordance with Approved procedures Shall also be maintained between the line and other Apparatus and objects.
- 6.3.8 With the exception of Approved Hot Glove Procedures; no vehicle, or person other than a member of the team doing the work, Shall be allowed in the near vicinity of the point of work while work is in progress without the sanction of the Authorised Person in charge of the High Voltage Live Line Work. Where mobile platforms etc. are used for access, the limits of movement of the platform Shall be established by the Authorised Person in charge of the High Voltage Live Line Work and strictly controlled so as to ensure that no metalwork, or any part of the platform, places any person in a position of Danger.
- 6.3.9 Before any pole is climbed it Shall be tested in an Approved manner. No pole badly impaired by decay or damage or whose stability is in doubt Shall be climbed until it has been supported by Approved means. The pole Shall then either be climbed by only one Person at a time, or access to the top of such pole Shall be by Approved means independent of the pole.
- 6.3.10 Before any pole is climbed and during the course of High Voltage Live Line Work the Authorised Person in charge Shall take all reasonably practicable steps to avoid Danger from steelwork being Live or becoming Live, in accordance with Approved procedures.

SSEN Distribution Operational Safety Manual Section 15 – High Voltage Live Line Work.

- 6.3.11 With the exception of Approved Hot Glove Procedures; where Approved procedures for High Voltage Live Line Work are based specifically on the use of insulating rods, no Person Shall climb, move or work in such a position as to bring any part of their body, clothing or any working tool (other than insulated High Voltage Live Line Work tools or equipment Approved for those procedures) within the Working and Access Clearances referred to in Rule 4.4.4 from Live exposed High Voltage Apparatus and, where appropriate, a marker or markers Shall be placed on the pole or tower as an indication (see also Appendix A, Diagrams 5 and 6).
- 6.3.12 On completion of the High Voltage Live Line Work, the Control Engineer Shall be informed when all Persons and tools have been withdrawn from the point of work.

7. SAFETY PRECAUTIONS FOR THE TESTING OF HIGH VOLTAGE APPARATUS

7.1 GENERAL

Testing of **High Voltage Apparatus** might involve a change of state from a condition of **Dead** to **Live Conductor**, possibly involving the issue and cancellation of a **Permit-to-Work** prior to the issue of a **Sanction-for-Test**. It is the duty of the issuer of the **Sanction-for-Test** to avoid **Danger** during the testing by undertaking a risk assessment and identifying appropriate control measures that **Shall** be implemented by the **Person** carrying out the testing. This should take into account the types of test being carried out, the location of the **Apparatus** being tested and its accessibility to **SSEN-D** staff, contractors, members of the public, etc. To allow reasonable flexibility during testing and, at the same time, to ensure the maintenance of appropriate safety standards, the following Rules of this Section require that an **Authorised Person Shall** assume special responsibility in this respect. SSEN Distribution Operational Safety Manual Section 9.1 – Testing of High Voltage Apparatus.

Please see the SSEN Distribution Approved Tools and Equipment list and catalogue (available via SSEN Distribution intranet pages) for Approved Voltage testing devices.

SSEN Distribution Operational Safety Manual Section 9.1 – Testing of High Voltage Apparatus.

Page 116 of 158

7.2 WORK UNDER THE TERMS OF A SANCTION-FOR-TEST

Any Apparatus which has been **Isolated** and **Earthed** for testing under the terms of a Sanction-for-Test Shall not be connected to the System until such Apparatus has passed the Approved tests and then, connected only with the sanction of the Control Engineer. The recipient of the Sanctionfor-Test Shall be responsible for co-ordinating all testing operations on the **Isolated** equipment and for ensuring safety during the tests. They may, without further reference to the Control Engineer, remove and replace Circuit Main Earths as necessary and carry out tests including making Live the Apparatus concerned from a testing supply. The recipient of the Sanction-for-Test Shall either make the tests personally or such tests Shall be carried out under their **Personal Supervision** so as to ensure safety at all times. The re-application of Circuit Main Earths at the end of testing might not be necessary. If an Approved procedure applies, the Circuit Main Earths may be left removed and reported to the Control Engineer as exceptions on the Sanction-for-Test. Otherwise, each Circuit Main Earth removed by the recipient of the Sanction-for-Test Shall be replaced before the signing of the clearance section of the Sanction-for-Test

7.3 TESTING OF HIGH VOLTAGE APPARATUS

- 7.3.1 When any High Voltage Apparatus is to be subjected to test voltage before being connected or reconnected to the High Voltage System, the Authorised Person responsible for applying the test voltage Shall ensure that such Apparatus and the associated test equipment, leads and connections are adequately guarded to prevent Danger. Danger Notices Shall be attached in conspicuous positions during the period the Apparatus might be subject to voltage. All cables and capacitors Shall be discharged before and after the application of test voltage.
- **7.3.2** Temporary **Conductors** used for testing purposes **Shall** be of an adequate size and be easily visible.
- 7.3.3 Test connections Shall not be applied in a cell or compartment in which there is any exposed metal Live at High Voltage. This Rule does not preclude the use of Approved voltage testing devices or other Approved devices for testing and phasing out circuits in an Approved manner.
- 7.3.4 The requirements of Rule 4.4 **Shall** be observed in respect of access or work in the proximity of **Live** test leads and connections and in respect of testing in the vicinity of **Live Conductors**.

Please see the SSEN Distribution Approved Tools and Equipment list and catalogue (available via SSEN Distribution intranet pages) for Approved earthing/ bonding equipment.

For Approved Procedure please reference the SSEN Distribution Operational Safety Manual Section 10 – Low Voltage Work and Testing.

Page 118 of 158

8. SAFETY PRECAUTIONS AND PROCEDURES APPLICABLE TO LOW VOLTAGE SYSTEMS

8.1 GENERAL

- 8.1.1 The term Low Voltage System and this section of the OSR applies to the System operating at Low Voltage.
- 8.1.2 When work or testing is carried out on or near Low Voltage Apparatus and Conductors, precautions Shall be taken to prevent Danger from burn injury due to electrical arc and from electric shock, if the Conductors are exposed. These precautions are necessary to prevent Danger to Competent Persons and, so far as reasonably practicable, Danger to Third-Parties, i.e. persons that may not have sufficient technical knowledge and/or experience to enable them to maintain safety from the System.

If the **Conductors** are covered with insulation and screening, the adequacy of these materials to prevent **Danger Shall** be assessed by a **Competent Person** with regard to the nature of the work or testing. Where necessary the precautions appropriate to work on or near exposed **Conductors Shall** be applied. **Danger** may arise in the following circumstances:

- (a) a **Person** incorrectly identifies **Apparatus** and **Conductors** which have been made **Dead** with those which remain **Live**;
- (b) Dead Apparatus and Conductors are accidentally or inadvertently made Live, either from the System or via generators and/or other Distributed Energy Resources on the consumer's side of the interface with the System;
- (c) a **Person** accidentally or inadvertently makes contact with adjacent **Live Conductors;** or
- (d) inadequate precautions are taken during **Live** work or testing.
- 8.1.3 The term 'Earthed' when applied to Low Voltage Systems means the bonding of all the phase Conductors (including any switch or Earth wire) to the neutral Conductor by means of an Approved device or Approved leads.

SSEN Distribution Operational Safety Manual Section 2.6 – Co-ordination of Work and Operations on the Low Voltage System.

SSEN Distribution Operational Safety Manual Section 10 – Low Voltage Work and Testing.

SSEN Distribution Operational Safety Manual Section 10 – Low Voltage Work and Testing

SSEN Distribution Operational Safety Manual Section 7 – Access and Work on High Voltage Overhead Lines.

- 8.1.4 Control and operation of Low Voltage Systems Shall be in accordance with an Approved procedure. Only Persons appointed in accordance with an Approved procedure Shall have authority to carry out activities such as Switching and the Live testing of Low Voltage Systems.
- 8.1.5 Work on, or testing of Low Voltage Apparatus and Conductors Shall only be carried out by a Competent Person. Where working arrangements so require, Approved procedures for the control of work, including the issue of a Safety Document, Shall apply.
- 8.1.6 Where work or testing involves the initial connection, or the rearrangement of **Conductors** to a consumer, supply **Shall** not be commenced or recommenced to that consumer until checks to ensure correct polarity, rotation and earthing arrangements are in compliance with an **Approved** procedure.
- 8.1.7 No Low Voltage overhead line Shall be erected or dismantled under a Live High Voltage overhead line without the authority of a Senior Authorised Person who Shall ensure that when necessary, for example because of insufficient clearance, the High Voltage line is made Dead and a Permit-to-Work issued. The Permit-to-Work Shall detail the Low Voltage work to be carried out. When a Low Voltage overhead line Conductor is to be raised or lowered or otherwise held on temporary supports/ connections. Approved procedures Shall be followed to ensure that no Danger is caused at locations such as road/ rail crossing etc. where other persons may be present.
- 8.1.8 When work or testing on the Low Voltage System is planned, precautions Shall be taken to safeguard the integrity of the Low Voltage System and in the process prevent, so far as reasonably practicable, Danger to Third-Parties, i.e. persons that may not have sufficient technical knowledge and/or experience to enable them to maintain safety from the System.

System Control Principle – only one Person can be in control of any part of the System at any one point in time.

8.2 GENERAL REQUIREMENTS FOR WORK ON DEAD LOW VOLTAGE APPARATUS AND CONDUCTORS

- 8.2.1 When work is to be carried out on **Dead Low Voltage Apparatus** the **Conductors Shall** be **Isolated** from all sources of supply from the **System**. Where the **Isolating Devices** are lockable, **Safety Locks Shall** be applied. If components such as fuses and links are removable they **Shall** be removed. **Caution Notices Shall** be securely fixed at all points of isolation. Keys and removed components **Shall** be kept in a secure place.
- 8.2.2 The Conductors Shall be Earthed where an earthing device or earthing leads are Approved for use on the Conductors concerned.
- 8.2.3 Except when work on a Low Voltage System is being carried out as part of Approved High Voltage Live Line Work, the following requirements Shall apply:
 - (a) if the work requires a point of isolation to be established on a High Voltage System, a Safety Document Shall be issued with the consent of the Control Engineer of the High Voltage System;
 - (b) if the work requires a High Voltage System to be made Dead, Isolated and Earthed, a Permit-to-Work Shall be issued; or
 - (c) if the work is being done in conjunction with work on the High Voltage System which has been made Dead, Isolated and Earthed, then unless the Low Voltage work is included on the Permit-to-Work issued for the High Voltage work, a separate Safety Document for the Low Voltage work Shall be issued, with the consent of the Control Engineer of the High Voltage System.
- 8.2.4 Suitable precautions Shall be taken by Approved screening or other Approved means to avoid Danger from inadvertent contact with adjacent Live Conductors including, where necessary, the fixing of Danger Notices to Apparatus containing Live Conductors, adjacent to other Live Conductors and at the limits of the zone of work.

SSEN Distribution Operational Safety Manual Section 10 – Low Voltage Work and Testing.

SSEN Distribution Operational Safety Manual Section 10 – Low Voltage Work and Testing.

Please see the SSEN Distribution Approved Tools and Equipment list and catalogue (available via SSEN Distribution intranet pages) for Approved Voltage testing devices.

SSEN Distribution Operational Safety Manual Section 10.2 – Work on Damaged or Faulty Low Voltage Cables.

Page 124 of 158

- 8.2.5 Where Conductors may become Live due to the operation of a consumer's generator, or embedded Distributed Energy Resources; one or more of the following precautions Shall be taken to prevent Danger:
 - the Conductors Shall be Isolated from the consumer's System;
 - (b) the **Conductors Shall** be **Earthed** or an **Earth** provided between the point of work and the consumer's **System**; and
 - (c) the work **Shall** be carried out in accordance with Rule 8.5 and Rules 8.6 or 8.7 as appropriate.
- 8.2.6 Before work is commenced, the Apparatus and Conductors Shall be identified and proved Dead at the point of work by means of an Approved voltage testing device. Whilst work is in progress, any Live working methods that can reasonably be applied to minimise the risk of Danger from the Conductors being accidentally or inadvertently made Live Shall be used.

8.3 ADDITIONAL PRECAUTIONS FOR WORK ON DEAD LOW VOLTAGE CABLES

- 8.3.1 The cable to be worked on Shall be identified in accordance with an Approved procedure which Shall include the following:
 - (a) all damaged cables **Shall** be treated as **Live** until identified and proved **Dead** by an **Approved** procedure;
 - (b) unless the point of work can be physically traced from a point where the Conductors are accessible and have been proved Dead at that point, it will normally be necessary to open the cable as if it is Live and test each Conductor with an Approved voltage testing device; or
 - (c) if the cable has been damaged or is faulty, this test Shall be made at a safe distance from the suspected point of damage/ fault, unless an Approved procedure has specific provisions which allow testing at the point of damage. The cable Shall then be physically traced from the point of test to the suspect point of damage/ fault. Appropriate precautions Shall be taken to avoid Danger from electric shock and explosive arcing until the point of damage/ fault is located and the cable made Dead.

SSEN Distribution Operational Safety Manual Section 8 – Access and Work on High Voltage Underground Cables.

Please see the SSEN Distribution Approved Tools and Equipment list and catalogue (available via SSEN Distribution intranet pages) for Approved earthing equipment.

SSEN Distribution Operational Safety Manual Section 10 – Low Voltage Work and Testing.

SSEN Distribution Operational Safety Manual Section 10 – Low Voltage Work and Testing.

8.3.2 When work is to be carried out on an auxiliary cable which may be subject to induced voltage from a **High Voltage** circuit, additional precautions to prevent **Danger** from these voltages **Shall** be taken in accordance with **Approved** procedures.

8.4 ADDITIONAL PRECAUTIONS FOR WORK ON DEAD LOW VOLTAGE OVERHEAD LINES

- 8.4.1 Bare open-wire Low Voltage Conductors Shall be Earthed using Approved earthing leads. Where insulated but unscreened Conductors are present, the requirements for Live working Shall be observed until the Conductors have been proved Dead.
- 8.4.2 Any unearthed steelwork such as an offset bracket or the upper portion of a stay above the insulator **Shall** be treated as **Live** until it or the **Conductors** have been proved **Dead**.

8.5 WORK ON LIVE LOW VOLTAGE APPARATUS AND CONDUCTORS

- 8.5.1 No Low Voltage Live work Shall be carried out except in accordance with an Approved procedure. This Approved procedure Shall adequately prevent Danger from electric shock and inadvertent short-circuiting of the Conductors.
- 8.5.2 Where Live work is to be carried out under an Approved procedure, the Competent Person in charge of the Working Party Shall make an assessment of the site conditions. Live work Shall only be commenced where site conditions enable the work to be carried out safely. If the site conditions become unfavourable Live working Shall be suspended. In particular the following requirements Shall be assessed:
 - (a) the **Apparatus** to be worked upon **Shall** be visually inspected to see that it is in a satisfactory condition;
 - (b) there Shall be adequate working space and safe means of egress;
 - (c) the working space and the **Apparatus** to be worked on **Shall** be adequately illuminated; and
 - (d) if the work is outdoors the weather conditions **Shall** not be unduly adverse.

SSEN Distribution Operational Safety Manual Section 10 – Low Voltage Work and Testing.

Please see the SSEN Distribution Approved Tools and Equipment list and catalogue (available via SSEN Distribution intranet pages) for Approved equipment and Voltage testing devices.

- 8.5.3 All Persons who carry out Live working Shall be Competent Persons and Shall have received appropriate training in the particular Approved procedure. They Shall be adequately instructed by the Competent Person in charge of the Working Party.
- 8.5.4 Only tools and equipment **Approved** for that purpose **Shall** be used for work on, or the testing of, **Live Low Voltage Apparatus** and **Conductors**.
- 8.5.5 No Person Shall carry out work which involves, or is equivalent to, the manipulation of bare Live Conductors unless accompanied by another Person who Shall be available to render or obtain assistance in an emergency.

8.6 ADDITIONAL PRECAUTIONS FOR WORK ON LIVE LOW VOLTAGE CABLES

- 8.6.1 The cable to be worked on Shall be identified by an Approved means. All metalwork adjacent to the point of work Shall be adequately shrouded with Approved insulating material to prevent inadvertent contact. The metallic sheaths of cables Shall be bonded to each other with an Approved insulated Conductor before jointing and before cutting to ensure continuity of the electrical circuit through the sheath.
- 8.6.2 Unless alternative Approved procedures allow, during all work, including the change of cut-outs, only one Conductor Shall be bared at a time and as a minimum Approved insulating gloves Shall be used.

8.7 ADDITIONAL PRECAUTIONS FOR WORK ON LIVE LOW VOLTAGE OVERHEAD LINES

- 8.7.1 Where work is carried out on Live overhead lines, any unearthed steelwork such as an offset bracket or the upper portion of a stay above the insulator Shall be proved Dead using an Approved voltage testing device.
- 8.7.2 When work is carried out on insulated but unscreened Low Voltage Conductors Approved insulating gloves Shall be worn and Approved insulated tools used to prevent Danger that may arise if the insulation has deteriorated or is damaged.

SSEN Distribution Operational Safety Manual Section 10 – Low Voltage Work and Testing.

Please see the SSEN Distribution Approved Tools and Equipment list and catalogue (available via SSEN Distribution intranet pages) for Approved equipment and Voltage testing devices.

8.8 APPLICATION OF HIGH VOLTAGE RULES TO WORK ON LOW VOLTAGE APPARATUS AND CONDUCTORS

8.8.1 Where OSR applicable to work on High Voltage Systems, Apparatus and Conductors are applied to Low Voltage Systems, Apparatus and Conductors, this Shall be in accordance with Approved procedures.

8.9 TESTING AND ADJUSTMENT OF LIVE LOW VOLTAGE APPARATUS

- 8.9.1 Testing and adjustment, including functional testing, may be made with Low Voltage Apparatus Live provided that Approved insulated tools and instruments are used.
- 8.9.2 If the testing or adjustment requires covers to be removed so that terminals or connections that are Live, or can be made Live, are exposed or temporarily disconnected, then precautions Shall be taken to prevent unauthorised access to or interference with the Apparatus. Such precautions Shall include, where necessary, Personal Supervision and/or erection of suitable barriers or screening and the display of Danger Notices.
- 8.9.3 If the Conductors are to be made Dead in order to avoid Danger, then the requirements of Safety Rules 8.2, 8.3 and 8.4 Shall be applied.

SSEN Distribution Operational Safety Rules 2022

If you're not sure, stop and ask for help.

Page 132 of 158

9. RESPONSIBILITIES OF PERSONS

9.1 GENERAL

- 9.1.1 It is the duty of all **Persons** who may be concerned with the control, operation, work or testing, on or in the near vicinity of **Apparatus** and **Plant** to which these **OSR** apply, to implement the **OSR** and to comply with them and with related Codes and Procedures. Ignorance of the relevant legal requirements, **OSR** and Codes or Procedures **Shall** not be accepted as an excuse for neglect of duty.
- **9.1.2** The responsibilities placed upon **Persons** may include all or part of those detailed in this section, depending on the role of the **Persons**.
- **9.1.3** Any written authorisation given to **Persons** to perform their designated role in implementing the **OSR Shall** indicate the class of operation and/or work permitted and the section of **System** to which the authorisation applies.
- 9.1.4 Persons involved in achieving safety from the inherent Dangers of the System to allow work or testing to commence on Apparatus and Plant and its subsequent restoration to service, will be concerned in separate broadly identifiable areas of responsibility, as follows:
 - control including (before work commences) instructing actions to implement precautions and sanctioning the issue of Safety Documents and (after completion of work) acknowledging cancellation of Safety Documents and instructing actions to restore Apparatus and Plant to service;
 - making safe or restoration of Apparatus and Plant including (before work commences) taking action to make Apparatus and Plant safe for work and issuing Safety Documents and (after completion of work) cancelling Safety Documents and taking action to restore Apparatus and Plant to service; and
 - (iii) work which includes receipt of a Safety Document, execution of the required work to its completion or termination and clearance of the Safety Document.

Reminder – safety rule 1.7 can be used for objections on safety grounds.

9.2 COMPETENT PERSONS

- 9.2.1 The responsibilities of Competent Persons include those specified below. Competent Persons Shall ensure that their responsibilities are implemented. Competent Persons who may be nominated to be responsible for the Supervision of a Working Party, Shall be appointed in writing.
- **9.2.2** Competent Persons Shall comply with these OSR when carrying out work whether instructions are issued orally or in writing.
- **9.2.3 Competent Persons Shall** use safe methods of work, safe means of access and the personal protective equipment and clothing provided for their safety.
- 9.2.4 Competent Persons when responsible for the Supervision of a Working Party Shall:
 - (i) Be responsible for establishing and maintaining the **General Safety** of the **Working Party**;
 - be fully conversant with the nature and the extent of the work to be done;
 - (iii) read the contents and confirm to the **Person** issuing any **Safety Document** that they are fully understood;
 - during the course of the work, adhere to, and instruct others under their charge to adhere to, any conditions, instructions or limits specified on any Safety Document;
 - (v) retain any Safety Document and (where appropriate) keys in safe custody and correctly implement any SSEN-D procedure to achieve this; and
 - (vi) provide Immediate or Personal Supervision as required; and warn all persons as quickly as possible to withdraw from and not work on the Apparatus and Plant concerned until further notice, if during the course of work a hazard arises or is suspected, which could result in Danger. The situation Shall be reported immediately by the Competent Person to a Senior Authorised Person or Control Engineer.
- 9.2.5 Competent Persons Shall not start or restart work under a Safety Document issued to another Competent Person without the permission of that other Competent Person.



Have you registered?

Page 136 of 158

9.2.6 Competent Persons clearing a Safety Document Shall do so only after all persons working under the Safety Document have been withdrawn from, and warned not to work on, the Apparatus and Plant concerned. Where appropriate, they Shall ensure that all tools, gear and loose material have been removed, guards and access doors replaced and the workplace left tidy. Where appropriate they Shall also return, or account for, the correct number of Additional Earths, circuit identification flags and wristlets and associated keys and documents.

9.3 AUTHORISED PERSONS

- 9.3.1 In addition to responsibilities as **Competent Persons**, **Authorised Persons Shall** have some, or all of the following responsibilities within the limits imposed by their Certificates of Authorisation.
- **9.3.2** When participating in achieving safety from the inherent **Dangers** of the **System, Authorised Persons Shall** correctly implement specified procedures before work commences, including all of the following:
 - the keeping of a proper record of all verbal messages passed by telephone or otherwise, relating to the operation of the High Voltage System;
 - the reading back to the sender of every such message relating to the operation of the High Voltage System to ensure that the message has been accurately received; and
 - (iii) carrying out operations instructed by the Control Engineer without unnecessary delay, the implementation of the instructions to be reported back to the Control Engineer as soon as possible after completion.
- **9.3.3** As the recipient of a **Sanction-for-Test** an **Authorised Person** is responsible for all of the following:
 - meeting the particular requirement of Section 7 of these OSR;
 - being present during the testing, being responsible for coordinating all testing operations on the **Isolated** equipment and for ensuring safety during the tests. Such tests may include making **Live** the **Apparatus** and **Plant** from a testing supply; and

Did you know – more than 95% of operational incidents are caused by reduced concentration by the Persons involved.

- carrying out the temporary removal and re-application of Earths as necessary without further reference to the Control Engineer.
- 9.3.4 When given the authority to issue and cancel a Limitation-of-Access, to ensure:
 - that the recipient of the Limitation-of-Access understands the nature and extent of the work to be undertaken and the safety precautions to be taken; and
 - (ii) where applicable, the authority of the **Control Engineer** has been obtained for the issue of the **Safety Document**.

9.4 SENIOR AUTHORISED PERSONS

- 9.4.1 In addition to responsibilities as Authorised Persons, Senior Authorised Persons Shall have some or all of the following responsibilities.
- 9.4.2 Correctly implementing Approved procedures to ensure that all precautions to achieve safety from the inherent Dangers or the System are completed, including:
 - (i) confirming through the **Control Engineer** that safety precautions at all locations are complete; and
 - (ii) meeting the requirements of the relevant sections of these **OSR**.
- **9.4.3** Prior to the issue of a **Safety Document**, deciding where appropriate:
 - whether Additional Earths are required, and if so, the number and points of application;
 - whether any action is required to contain or dissipate stored energy;
 - (iii) whether any additional precautions are necessary;
 - (iv) whether **Personal Supervision** is required, and also ensuring that:
 - safety from the inherent **Dangers** of the **System** has been achieved and will be maintained when the requirements of the **Safety Document** are completely implemented;

Reminder – on average adults can process approx. 7 +/- 2 chunks of information, if you try to process more than this when operating, you're likely to make a mistake.

- (vi) the contents of the **Safety Document** to be issued are correct and unambiguous; and
- (vii) the authority of the Control Engineer has been obtained for the issue of a Permit-to-Work or Sanction-for-Test.

9.4.4 When issuing a Safety Document:

- fully explaining the contents of the Safety Document to the recipient and ensuring that the recipient understands the nature and extent of the work or testing to be done and the safety precautions to be taken; and
- (ii) issuing the Safety Document together with (as appropriate) any keys, circuit identification flags and wristlets and noting all Additional Earths, and documenting where additional precautions have to be taken.

9.4.5 When cancelling a Safety Document:

- ensuring that the requirements of the clearance section have been completed correctly;
- (ii) checking that all items issued with the **Safety Document** have been returned or accounted for;
- checking the operational state of the Apparatus and Plant; and
- (iv) informing the Control Engineer of the cancellation of the document and confirming the operational state of the Apparatus and Plant.
- 9.4.6 When a Senior Authorised Person is in control of a System then their responsibilities Shall extend to embody those of a Control Engineer as set out in Rule 9.5 whilst they have control of that System.

SSEN Distribution Operational Safety Manual Section 2 – System Control.

SSEN Distribution Operational Safety Manual Section 4 – System Operations.

9.5 CONTROL ENGINEERS

- **9.5.1** The responsibilities of **Control Engineers** within their sphere of operation which arise from the implementation of these **OSR** include the following:
 - giving authority for the release of Apparatus and Plant from service;
 - (ii) giving authority for all **High Voltage Switching** except in cases of emergency or in other **Approved** cases;
 - communicating directly via Approved means with the Authorised Person who is to carry out the Switching;
 - (iv) consulting with Control Engineers of other Systems to agree and initiate Switching where there is interconnection across control boundaries; also agreeing responsibility for control of circuits in the Isolated state preparatory to sanctioning the issue of Safety Documents;
 - before giving authority for the issue of a Safety Document to ensure that the necessary operations to obtain safety from the inherent Dangers of the System are carried out;
 - (vi) giving authority for the issue, and acknowledging cancellation of, Permits-to-Work and Sanctions-for-Test; and
 - (vii) maintaining an Approved record of all High Voltage Switching, application and removal of Circuit Main Earths and the issue and cancellation of Permits-to-Work, Sanctions-for-Test and, where applicable, Limitations-of-Access.

Reminder – when operating and/or working on the System, all Persons should have their Authorisation Certificate and Operational Safety Rule book with them.

10. APPENDIX A – WORKING AND ACCESS CLEARANCE DIAGRAMS

The **Working and Access Clearances** contained in the following diagrams and tables are derived from the **Safety Distances** 'X' specified in Rule 4.4.1 (Table 1) with the addition of "Application Factors" appropriate to the particular work activity.

Diagram 1:

Specifies the **Safety Distances** for Work on Overhead Lines Carrying **Live High Voltage Conductors** (Rule 4.4.1 refers).

Diagrams 2 & 3:

Specify the **Working and Access Clearances** for work on overhead lines carrying **Live High Voltage Conductors** (Rules 4.4.4 and 5.10.5.2 refer).

Diagram 4:

Specifies **Working and Access Clearances** for work in substations and switching stations containing exposed **Live High Voltage Conductors** (Rules 4.4.4 and 4.5.3 refer).


Diagram 5 & 6:

Specify **Working and Access Clearances** for **High Voltage Live Line Work** (Rules 4.4.4, 6.3.11 and 6.2.2 (Table 2) refer).

Reminder – safety rule 1.7 can be used for objections on safety grounds.

DIAGRAM 1 – STEEL TOWER (A REMINDER OF SAFETY DISTANCES)

Safety Distances for Work on Overhead Lines Carrying **Live High Voltage Conductors**, (Rule 4.4.1).




Voltage	Safety Distance 'X'	
11kV	0.8 m	
33kV	0.8 m	
66kV	1.0 m	
132kV	1.4 m	
275kV	2.4 m	
400kV	3.1 m	

Check – what's above you, below you, around you, that can hurt you?

DIAGRAM 2 – LADDERS OR CLIMBING IRONS

Working and Access Clearances for work on or adjacent to structures carrying Live High Voltage Conductors. (Rules 4.4.4/5.10.5.2).




Voltage	Safety Distance 'X'	Application Factor	Working and Access Clearance = 'A'
11kV	0.8 m	0.3 m	1.1 m
33kV	0.8 m	0.3 m	1.1 m
66kV	1.0 m	0.3 m	1.3 m
132kV	1.4 m	0.3 m	1.7 m
275kV	2.4 m	0.3 m	2.7 m
400kV	3.1 m	0.3 m	3.4 m

Reminder – safety rule 1.9 states that ignorance of rules and procedures can't be accepted as an excuse for neglect of duties.

DIAGRAM 3 – WORK PLATFORMS

Working and Access Clearances for work on or adjacent to structures carrying Live High Voltage Conductors. (Rules 4.4.4/5.10.5.2).




Voltage	Safety Distance = 'X'	Application Factor	Working and Access Clearance = 'A'	Platform Clearance 'B' = Safety Distance 'X' + 2.1m*
11kV	0.8 m	0.3 m	1.1 m	2.9 m
33kV	0.8 m	0.3 m	1.1 m	2.9 m
66kV	1.0 m	0.3 m	1.3 m	3.1 m
132kV	1.4 m	0.3 m	1.7 m	3.5 m
275kV	2.4 m	0.3 m	2.7 m	4.5 m
400kV	3.1 m	0.3 m	3.4 m	5.2 m

* The Platform Application Safety Factor of 2.1m is an absolute minimum. The vertical **Working and Access Clearances** from a platform below a **Live Conductor Shall** be established such that the **Working and Access Clearance** "A" is always maintained below the **Conductor**. This **Shall** take into account the height of the people doing the work, the tools used and the nature of the work.

Reminder – substations and switching sites with low-level exposed high voltage conductors are high-risk hazardous environments – leave complacency at the gate.

DIAGRAM 4 – SUBSTATIONS AND SWITCHING STATIONS

Working and Access Clearances for Work in Substations and Switching Stations Containing Exposed **Live High Voltage Conductors**, (Rules 4.4.4/4.5.3).



Voltage	Safety Distance 'X'	Horizontal Application Factor	Horizontal Working and Access Clearance 'C'	Platform Clearance 'B' = Safety Distance 'X' + 2.1m*
11kV	0.8 m	1.5 m	2.3 m	2.9 m
33kV	0.8 m	1.5 m	2.3 m	2.9 m
66kV	1.0 m	1.5 m	2.5 m	3.1 m
132kV	1.4 m	1.5 m	2.9 m	3.5 m
275kV	2.4 m	1.5 m	3.9 m	4.5 m
400kV	3.1 m	1.5 m	4.6 m	5.2 m

*The Platform Application Safety Factor of 2.1m is an absolute minimum. The vertical **Working and Access Clearances** from a platform below a **Live Conductor Shall** be established such that the **Safety Distance** is always maintained below the **Conductor**. This **Shall** take into account the height of the people doing the work, the tools used and the nature of the work.


SSEN Distribution Operational Safety Rules 2022

We see it, sort it, report it.

Page 154 of 158

DIAGRAM 5 – HV LIVE LINE WORK USING LADDERS OR CLIMBING IRONS (Excluding Approved Hot Glove Procedures)

Working and Access Clearances for High Voltage Live Line Work. (Rules 4.4.4, 6.3.11 and 6.2.2)



Voltage	Safety Distance 'X'	Application Factor = 'Y'	Working and Access Clearance = 'A'
11kV	0.8 m	0.3 m	1.1 m
33kV	0.8 m	0.3 m	1.1 m
66kV	1.0 m	0.3 m	1.3 m
132kV	1.4 m	0.3 m	1.7 m
275kV	2.4 m	0.3 m	2.7 m
400kV	3.1 m	0.3 m	3.4 m


SSEN Distribution Operational Safety Rules 2022

If it's not safe, we don't do it.

Page 156 of 158

DIAGRAM 6 – HV LIVE LINE USING WORK PLATFORMS (Excluding Approved Hot Glove Procedures)

Working and Access Clearances for **High Voltage Live Line Work**, (Rules 4.4.4, 6.3.11 and 6.2.2)



Voltage	Safety Distance = 'X'	Application Factor = 'Y'	Working and Access Clearance = 'A'	Platform Clearance 'B' = Safety Distance 'X' + 2.1m*
11kV	0.8 m	0.3 m	1.1 m	2.9 m
33kV	0.8 m	0.3 m	1.1 m	2.9 m
66kV	1.0 m	0.3 m	1.3 m	3.1 m
132kV	1.4 m	0.3 m	1.7 m	3.5 m
275kV	2.4 m	0.3 m	2.7 m	4.5 m
400kV	3.1 m	0.3 m	3.4 m	5.2 m

*The Platform Application Safety Factor of 2.1m is an absolute minimum. The vertical **Working and Access Clearances** from a platform below a **Live Conductor Shall** be established such that the **Working and Access Clearance** "A" is always maintained below the **Conductor**. This **Shall** take into account the height of the people doing the work, the tools used and the nature of the work.

Intentionally left blank.


Page 158 of 158

Intentionally left blank.

Produced by Lithgo Press Ltd. 10 Ashville Way, Whetstone. Leicester. LE8 6NU.

Scottish and Southern Electricity Networks is a trading name of: Scottish and Southern Energy Power Distribution Limited Registered in Scottan Ao. Sc213469; Scottish Hydro Electric Power Distribution pic Registered in Scottan Ao. Sc213469; (all having their Registered of Scottan Ho. Sc213469; (all having their Registered of Mose at Inveralmond House 200 Dunkeld Road Perth PH1 3AQ); and Southern Electric Power Distribution pic Registered in England & Wales No. 04094200 having their Registered of Office at Inveralmond House 200 Dunkeld Road Perth PH1 3AQ); and Southern Electric Power Distribution pic Registered in England & Wales No. 04094200 having their Registered Office at No. 1 Forbury Place 43 Forbury Road Reading RG1 3JH which are members of the SSE Group www.sen.co.uk

EMERGENCY CPR GUIDANCE FOR ADULTS



- Approach, stop, think, act (remember DRAB – danger, response, airway, breathing).
- Apply barriers protect yourself.
- Speak to the casualty tell them your name.
- Tap collar bone and try to obtain a response.
- Open airway using head tilt, chin lift.
- Check for normal breathing take 10 seconds only to do this.
- Activate Emergency Medical Services (EMS) even if this means leaving the patient, but do not waste time searching for an AED (automated external defibrillator), or other support.
- 30 compressions in center of chest at a rate of 100-120 compressions per minute to a depth of 5-6 cm.
- Then open the airway and give 2 breaths up to 1 second or until you see the chest rise.
- The time between finishing the last compression, giving the 2 breaths and the next compression should ideally be 5 seconds with an absolute maximum of 10 seconds.
- Repeat until EMS/ AED arrives.
- If the patient regurgitates or vomits during CPR turn the patient onto their side facing away from you, turn their head and allow the vomit to drain out.
- Mouth to Nose ventilations is an option. To do this open the airway seal your hand over their mouth and blow in their nose while keeping the airway open.